

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/5/23	MAKE	KOMATSU	MODEL	WA320-5
SERIAL	60715	STAMP	W105-60715		
HR METER	18433	HR	Odometer	56789	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	20.5-25	YEAR	2005
				YR	

ENGINE : MODEL 6D102E-2 S/N	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn ファンガタあり FAN: LOOSE
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn フレーム露出あり FRAME: BARED
Glasses	FAIR · Attn *1
AirCon	A/C · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	FAIR · Attn 左右シリンダー油漏れ小 CYLINDERS: OIL LEAKING
Bell crank	FAIR · Attn
Bucket	FAIR · Attn にじみあり OIL OOZING
Articulate	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
リリーフ掛けるとエンストする	
ENGINE STALLING WITH ENGINE LOAD INCREASING	
A/C冷えない A/C: MALFUNCTION	
*1 左右ドアガラス欠、F右コーキング割れあり	
*1 DOOR GLASSES: PARTLY MISSING,	
RIGHT CAULKING PART OF WINDSHIELD: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。