

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/6/9	MAKE	KAWASAKI	MODEL	KLD70
SERIAL	NO PLATE			STAMP	KLD70-7364
HR METER	1217	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB	ROPS CNP / CNP / NONE	TIRE SIZE	20.5-25	

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn
Travel	FAIR	Attn
FOOT BRAKE	FAIR	Attn
PARKING BRAKE	FAIR	Attn 効かない MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR · DIRTY
Operator's Seat	FAIR	Attn ガタ、破れあり LOOSE, CUTS
Glasses	FAIR	Attn
AirCon	A/C	H/C · H only · C only · None
FRONT & CYLINDERS		
Arm	FAIR	Attn
Bell crank	FAIR	Attn
Bucket	FAIR	Attn *1
Articulate	FAIR	Attn *2

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER マルチプラウ MULTI PLOW
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
右側アーム横配管繋ぎ目油漏れ小	
CONNECTING PART OF PIPE AROUND RIGHT ARM: OIL LEAKING	
左CABドアヒンジ破損あり、ドア外れやすい	
UPPER LEFT DOOR HINGE: BROKEN (LEFT DOOR: EASY TO COME OFF)	
マルチプラウ開閉動作パワー弱い	
OPEN/CLOSE MOVEMENT OF MULTI PLOW: WEAK POWER	
*1 右シリンダー油漏れあり RIGHT CYLINDER: OIL LEAKING	
*2 左シリンダー油漏れあり LEFT CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。