

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/5/26	MAKE	IHI	MODEL	CCH500T
SERIAL No.	PLATE :	HS65	STAMP	NOT FOUND	
HR METER	1569	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	未確認 NOT CHECKED
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
BOOM		
MAIN BOOM		
BOOM TOTAL	34m	
TOP SHEAVE	<input checked="" type="radio"/> YES · NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり HUGE CUTS
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
左右キャタ緩みあり TRACK LINKS: WORN		
WEIGHT	2	
HOOK	50t, BALL	
LIFTER	YES · <input checked="" type="radio"/> NO	
COMMENT		
テレスコ、3段ブーム 3-SECTION TELESCOPIC BOOM		
起伏シリンダー油漏れ、ロッド傷あり		
DERRICKING CYLINDER: OIL LEAKING, SCRATCHED		
第3ドラム付 W/3rd DRUM		
ポンプ付近油漏れあり AROUND PUMP: OIL LEAKING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。