

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |           |
|-----------------|----------------------------------------|------|---------|-------------------|-----------|
| INSPECTION DATE | 2025/5/29                              | MAKE | KOMATSU | MODEL             | PC210-8N1 |
| SERIAL          | 314724                                 |      | STAMP   | KMTPC197H02314724 |           |
| HR METER        | ERROR                                  |      | HR      | YEAR              | YR        |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 600G              |           |

|                                  |                                    |                                   |            |
|----------------------------------|------------------------------------|-----------------------------------|------------|
| <b>ENGINE : MODEL</b>            |                                    | 6D107E-1                          | <b>S/N</b> |
| Oil leakage                      | FAIR · Attn                        |                                   |            |
| Blow-By                          | FAIR · Attn                        | A LITTLE · MIDDLE · SEVERE        |            |
| Sound                            | FAIR · Attn                        |                                   |            |
| Oil                              | FAIR · Attn                        |                                   |            |
| Exhaust Color                    | FAIR · Attn                        |                                   |            |
| US EPA                           | YES · NO                           |                                   |            |
| <b>MAIN PUMP</b>                 |                                    |                                   |            |
| Sound                            | FAIR · Attn                        |                                   |            |
| Oil leakage                      | FAIR · Attn                        |                                   |            |
| Power                            | FAIR · Attn                        |                                   |            |
| <b>COOLING SYSTEM</b>            |                                    |                                   |            |
| Radiator                         | FAIR · Attn                        |                                   |            |
| Oil Cooler                       | FAIR · Attn                        |                                   |            |
| <b>OPERATING SYSTEM</b>          |                                    |                                   |            |
| Swing                            | FAIR · Attn                        | ガタあり SWING: LOOSE                 |            |
| Travel                           | FAIR · Attn                        |                                   |            |
| <b>INTERIOR See Photos. 写真参照</b> |                                    |                                   |            |
| INTERIOR COND.                   | CLEAN · FAIR · DIRTY               |                                   |            |
| Operator's Seat                  | FAIR · Attn                        |                                   |            |
| Glasses                          | FAIR · Attn                        |                                   |            |
| AirCon                           | A/C · H/C · H only · C only · None |                                   |            |
| <b>BOOM / ARM / BKT</b>          |                                    |                                   |            |
| Boom                             | FAIR · Attn                        |                                   |            |
| Boom Cylinder                    | FAIR · Attn                        | 左油漏れあり LEFT CYLINDER: OIL LEAKING |            |
| Arm                              | FAIR · Attn                        | 自然降下あり HYDRAULIC DRIFT            |            |
| Arm Cylinder                     | FAIR · Attn                        |                                   |            |
| BKT                              | FAIR · Attn                        | ガタあり LOOSE                        |            |
| BKT Cylinder                     | FAIR · Attn                        |                                   |            |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。