

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/29	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	32742			STAMP	KMTPC189C01032742
HR METER	9045	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL 4D95LE-5 S/N 550315

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	ゴリゴリ感、ガタあり RATTLING, SWING: LOOSE
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	左側にじみあり LEFT CYLINDER: OIL OOZING
Arm	FAIR	Attn	ガタあり LOOSE
Arm Cylinder	FAIR	Attn	にじみあり OIL OOZING
BKT	FAIR	Attn	ガタあり LOOSE
BKT Cylinder	FAIR	Attn	にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

.....

.....

.....

.....

.....

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG WRIST

Multi MULTI 2 NO

ARM-CRANE YES NO

BLADE YES NO

OFFSET YES NO

OFFSET Cylinder FAIR Attn

Piping YES NO Breaker only Multi

COMMENT

ブーム背面ホースひび割れあり
SOME HOSE AROUND LOWER PART OF BOOM: CRACKED

.....

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。