

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/5/26	MAKE	KOMATSU	MODEL	WA100-7
SERIAL	86109			STAMP	WA124-86109
HR METER	9173	HR	Odometer	28650	km YEAR YR
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			TIRE SIZE	16.9-24

ENGINE : MODEL 4D95LE-6 S/N 707439	
Oil leakage	<u>FAIR</u> • Attn
Blow-By	<u>FAIR</u> • Attn A LITTLE • MIDDLE • SEVERE
Sound	<u>FAIR</u> • Attn
Oil	<u>FAIR</u> • Attn
Exhaust Color	<u>FAIR</u> • Attn
US EPA	YES • <u>NO</u>
OPERATION PUMP	
Sound	<u>FAIR</u> • Attn
Oil leakage	<u>FAIR</u> • Attn
Power	<u>FAIR</u> • Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> • Attn
Oil Cooler	<u>FAIR</u> • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<u>PS</u> • DD
Transmission	<u>FAIR</u> • Attn
Travel	<u>FAIR</u> • Attn
FOOT BRAKE	<u>FAIR</u> • Attn
PARKING BRAKE	<u>FAIR</u> • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY
Operator's Seat	<u>FAIR</u> • Attn 破れあり CUT
Glasses	<u>FAIR</u> • Attn *1
AirCon	A/C • H/C • H only • C only • <u>None</u>
FRONT & CYLINDERS	
Arm	<u>FAIR</u> • Attn
Bell crank	<u>FAIR</u> • Attn
Bucket	<u>FAIR</u> • Attn
Articulate	<u>FAIR</u> • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR • WORN • <u>UNEVEN WEAR</u>
COMMENT	
STEERING TYPE <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	<u>YES</u> • NO
ATTACHMENTS	
STD BKT	<u>YES</u> • OTHER
BLADE	YES • <u>NO</u> Piping for Tilt <u>YES</u> • NO
COMMENT	
ワンタッチ付 W/ONE-TOUCH	
*1 F左ひび割れ、フレームから一部外れあり	
*1 LEFT PART OF WINDSHIELD:	
CRACKED, PARTLY COME OFF FROM FRAME	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。