

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2025/5/30	CATEGORY	自走式破砕機 MOBILE CRUSHER		
MAKE	KOMATSU		MODEL	BR380JG-3	
SERIAL	5018		STAMP	NOT FOUND	
HR METER	5905	HR	Odometer	km	YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>		SHOE	500G	TIRE

ENGINE	MODEL 6D107E-3	S/N 26655156	
Oil leakage	<u>FAIR</u> ・ Attn	Oil	<u>FAIR</u> ・ Attn
Blow-By	<u>FAIR</u> ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color <u>FAIR</u> ・ Attn
Sound	<u>FAIR</u> ・ Attn	EPA	YES ・ <u>NO</u>

CONDITION	<u>FAIR</u> ・ Attn

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
--	---	-----------	---------------------------

COMMENT
左走行レバー戻り悪い LEFT TRAVEL LEVER: HARD TO RETURN
付属品:手すり HANDRAILS AS SPARE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
--	---	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。