

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2025/6/4	MAKE	SAKAI	MODEL	SV513D		
SERIAL	10313			STAMP	1SV54-10313		
HR METER	2415	HR	Odometer	-	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.1-26		

ENGINE : MODEL		S/N	UNDERCARRIAGE :		See Photos. 写真参照
Oil leakage	(FAIR) · Attn		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE	TIRE WEAR (FAIR) · WORN · UNEVEN WEAR		
Sound	(FAIR) · Attn		COMMENT		
Oil	(FAIR) · Attn				
Exhaust Color	(FAIR) · Attn				
US EPA	YES · (NO)				
OPERATION PUMP					
Sound	(FAIR) · Attn				
Oil leakage	(FAIR) · Attn				
Power	(FAIR) · Attn				
COOLING SYSTEM					
Radiator	(FAIR) · Attn				
Oil Cooler	(FAIR) · Attn				
TRANSMISSION & TRAVEL					
T/M TYPE	(PS) · DD				
Transmission	(FAIR) · Attn				
Travel	(FAIR) · Attn				
FOOT BRAKE	(FAIR) · Attn				
PARKING BRAKE	(FAIR) · Attn				
INTERIOR See Photos. 写真参照					
INTERIOR COND.	(CLEAN)	FAIR · DIRTY			
Operator's Seat	(FAIR) · Attn				
Glasses	(FAIR) · Attn				
AirCon	(A/C) · H/C · H only · C only · None				
OTHERS					
Vibratory	(FAIR) · Attn				
Watering	(FAIR) · Attn				
Articulate	(FAIR) · Attn		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		
			5		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。