

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2025/6/2	MAKE	CAT	MODEL	CS56B
SERIAL	CATCS56BH48400203			STAMP	CATCS56BH48400203
HR METER	4596	HR	Odometer	—	km YEAR YR
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.1-26

ENGINE : MODEL C4.4 S/N W7N27938	UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage ☒ FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	
Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE	TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR	
Sound ☒ FAIR · Attn	COMMENT 	
Oil ☒ FAIR · Attn		
Exhaust Color ☒ FAIR · Attn		
US EPA YES ☒ NO		
OPERATION PUMP		
Sound ☒ FAIR · Attn		
Oil leakage ☒ FAIR · Attn		
Power ☒ FAIR · Attn		
COOLING SYSTEM		
Radiator ☒ FAIR · Attn		
Oil Cooler ☒ FAIR · Attn		
TRANSMISSION & TRAVEL		
T/M TYPE ☒ PS · DD		
Transmission ☒ FAIR · Attn		
Travel ☒ FAIR · Attn		
FOOT BRAKE FAIR · Attn		
PARKING BRAKE ☒ FAIR · Attn		
INTERIOR See Photos. 写真参照		
INTERIOR COND. CLEAN · ☒ FAIR · DIRTY		
Operator's Seat ☒ FAIR · Attn		
Glasses ☒ FAIR · Attn		
AirCon ☒ A/C · H/C · H only · C only · None		
OTHERS		
Vibratory ☒ FAIR · Attn		
Watering FAIR · Attn		
Articulate ☒ FAIR · Attn		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。