

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/6/5	MAKE	KOMATSU	MODEL	D20P-6
SERIAL	69734			STAMP	D206-69734
HR METER	ERROR	HR	SHOE	510LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		S/N	UNDERCARRIAGE See Photos. 写真参照	
Oil leakage	FAIR • Attn		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	COMMENT	
Sound	FAIR • Attn			
Oil	FAIR • Attn			
Exhaust Color	FAIR • Attn			
US EPA	YES • NO			
OPERATION PUMP			Ripper	MULTI • S/S Shanks PCS
Sound	FAIR • Attn		Ripper CYLD.	FAIR • Attn
Oil leakage	FAIR • Attn		EQUALIZER BAR	FAIR • Attn
Power	FAIR • Attn		COMMENT	
COOLING SYSTEM			左右サイドカバー欠 SIDE COVERS: MISSING	
Radiator	FAIR • Attn		*1 クラッチペダル戻り悪い CLUTCH PEDAL: HARD TO RETURN	
Oil Cooler	FAIR • Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	PS • DD	DIFF. STEERING	YES • NO	
Transmission	FAIR • Attn			
Travel	FAIR • Attn	*1		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN • FAIR • DIRTY			
Operator's Seat	FAIR • Attn	破れあり HUGE CUTS		
Glasses	FAIR • Attn			
AirCon	A/C • H/C • H only • C only • None			
BLADE & CYLINDERS				
BLADE	FAIR • Attn			
CYLD.(R)	FAIR • Attn			
CYLD.(L)	FAIR • Attn	油漏れあり OIL LEAKING		
TILT CYLD	FAIR • Attn	にじみあり OIL OOZING		
ANGLE CYLD	FAIR • Attn	右側油漏れあり RIGHT CYLINDER: OIL LEAKING	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。