

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/5	MAKE	KOBELCO	MODEL	SK007-2
SERIAL	PT01371			STAMP	NOT FOUND
HR METER	1013	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>			SHOE	180R

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	*1
Blow-By	FAIR ☒ Attn	A LITTLE ☐ MIDDLE ☐ SEVERE ☐
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	多い MUCH OIL
Exhaust Color	FAIR ☒ Attn	
US EPA	YES ☐ NO ☒	
MAIN PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	2速使えない 2nd GEAR: UNABLE TO USE
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☐ FAIR ☒ DIRTY ☐	
Operator's Seat	FAIR ☒ Attn	
Glasses	FAIR ☒ Attn	
AirCon	A/C ☐ H/C ☐ H only ☐ C only ☐ None ☒	
BOOM / ARM / BKT		
Boom	FAIR ☒ Attn	
Boom Cylinder	FAIR ☒ Attn	サビあり RUSTY
Arm	FAIR ☒ Attn	
Arm Cylinder	FAIR ☒ Attn	
BKT	FAIR ☒ Attn	
BKT Cylinder	FAIR ☒ Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
左可変脚シリンダー油漏れあり LEFT EXPANDABLE CYLINDER: OIL LEAKING	
腹下油漏れ小 BOTTOM: OIL LEAKING	
BKT ☒ STD ☐ SLOPE ☐ NARROW ☐ SKELETON ☐ OTHER ()	
Lever	LONG ☐ WRIST ☒
Multi	MULTI ☐ 2 ☒ NO ☐
ARM-CRANE	YES ☐ NO ☒
BLADE	YES ☒ NO ☐
OFFSET	YES ☐ NO ☒
OFFSET Cylinder	FAIR ☒ Attn
Piping	YES ☒ NO ☐ Breaker only ☐ Multi ☒
COMMENT	
スイングシリンダー油漏れ小、サビ小 SWING CYLINDER: OIL LEAKING, RUSTY	
右下足元カバー外れあり RIGHT PART OF FLOOR COVER: COME OFF	
*1 E/G上部燃料にじみあり UPPER PART OF ENGINE: FUEL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。