

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/6/2	MAKE	TCM	MODEL	860
SERIAL	66000129			STAMP	S09-00129
HR METER	E3154	HR	Odometer	21651	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE		20.5-25	

<table style="width: 100%;"> <tr> <td colspan="2">ENGINE : MODEL</td> <td>S/N</td> </tr> <tr> <td>Oil leakage</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Blow-By</td> <td>☒ FAIR · Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES · ☒ NO</td> <td></td> </tr> <tr> <td colspan="3">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil leakage</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Power</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil Cooler</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>☒ PS · DD</td> <td></td> </tr> <tr> <td>Transmission</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Travel</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>FOOT BRAKE</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>PARKING BRAKE</td> <td>FAIR · ☒ Attn</td> <td>効かない MALFUNCTION</td> </tr> <tr> <td colspan="3">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · FAIR · ☒ DIRTY</td> <td></td> </tr> <tr> <td>Operator's Seat</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Glasses</td> <td>FAIR · ☒ Attn</td> <td>左ドアガラス欠 LEFT DOOR GLASS: MISSING</td> </tr> <tr> <td>AirCon</td> <td>☒ A/C · H/C · H only · C only · None</td> <td></td> </tr> <tr> <td colspan="3">FRONT & CYLINDERS</td> </tr> <tr> <td>Arm</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Bell crank</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Bucket</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Articulate</td> <td>☒ FAIR · Attn</td> <td>ガタあり LOOSE</td> </tr> </table>	ENGINE : MODEL		S/N	Oil leakage	☒ FAIR · Attn		Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Sound	☒ FAIR · Attn		Oil	☒ FAIR · Attn		Exhaust Color	☒ FAIR · Attn		US EPA	YES · ☒ NO		OPERATION PUMP			Sound	☒ FAIR · Attn		Oil leakage	☒ FAIR · Attn		Power	☒ FAIR · Attn		COOLING SYSTEM			Radiator	☒ FAIR · Attn		Oil Cooler	☒ FAIR · Attn		TRANSMISSION & TRAVEL			T/M TYPE	☒ PS · DD		Transmission	☒ FAIR · Attn		Travel	☒ FAIR · Attn		FOOT BRAKE	☒ FAIR · Attn		PARKING BRAKE	FAIR · ☒ Attn	効かない MALFUNCTION	INTERIOR See Photos. 写真参照			INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY		Operator's Seat	☒ FAIR · Attn		Glasses	FAIR · ☒ Attn	左ドアガラス欠 LEFT DOOR GLASS: MISSING	AirCon	☒ A/C · H/C · H only · C only · None		FRONT & CYLINDERS			Arm	☒ FAIR · Attn		Bell crank	☒ FAIR · Attn		Bucket	☒ FAIR · Attn		Articulate	☒ FAIR · Attn	ガタあり LOOSE	<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE : See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>3</td> </tr> <tr> <td>TIRE WEAR</td> <td>☒ FAIR · WORN · UNEVEN WEAR</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">オイルパン下周り油漏れ小 BOTTOM OF OIL PAN: OIL LEAKING</td> </tr> <tr> <td colspan="2">ミッション下周り油漏れ小 BOTTOM OF TRANSMISSION: OIL LEAKING</td> </tr> <tr> <td colspan="2">STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING</td> </tr> <tr> <td>RIDE CONTROL</td> <td>YES · ☒ NO</td> </tr> <tr> <td colspan="2">ATTACHMENTS</td> </tr> <tr> <td>STD BKT</td> <td>☒ YES · OTHER</td> </tr> <tr> <td>BLADE</td> <td>YES · ☒ NO Piping for Tilt YES · ☒ NO</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">左サイドカバーラッチ掛からない、不良</td> </tr> <tr> <td colspan="2">LEFT SIDE COVER LATCH: MALFUNCTION</td> </tr> <tr> <td colspan="2">スピードメーター動作しない SPEED METER: NOT WORKING</td> </tr> <tr> <td colspan="2">HRメーターストップ HR METER: STOPPED</td> </tr> <tr> <td colspan="2">ファンベルト鳴きあり FAN BELT: NOISES</td> </tr> <tr> <td colspan="2">A/C風が出ない A/C: NOT BLOWING AIR</td> </tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">3</td> </tr> </table>	UNDERCARRIAGE : See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR	COMMENT		オイルパン下周り油漏れ小 BOTTOM OF OIL PAN: OIL LEAKING		ミッション下周り油漏れ小 BOTTOM OF TRANSMISSION: OIL LEAKING		STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING		RIDE CONTROL	YES · ☒ NO	ATTACHMENTS		STD BKT	☒ YES · OTHER	BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO	COMMENT		左サイドカバーラッチ掛からない、不良		LEFT SIDE COVER LATCH: MALFUNCTION		スピードメーター動作しない SPEED METER: NOT WORKING		HRメーターストップ HR METER: STOPPED		ファンベルト鳴きあり FAN BELT: NOISES		A/C風が出ない A/C: NOT BLOWING AIR		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
ENGINE : MODEL		S/N																																																																																																																																	
Oil leakage	☒ FAIR · Attn																																																																																																																																		
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE																																																																																																																																	
Sound	☒ FAIR · Attn																																																																																																																																		
Oil	☒ FAIR · Attn																																																																																																																																		
Exhaust Color	☒ FAIR · Attn																																																																																																																																		
US EPA	YES · ☒ NO																																																																																																																																		
OPERATION PUMP																																																																																																																																			
Sound	☒ FAIR · Attn																																																																																																																																		
Oil leakage	☒ FAIR · Attn																																																																																																																																		
Power	☒ FAIR · Attn																																																																																																																																		
COOLING SYSTEM																																																																																																																																			
Radiator	☒ FAIR · Attn																																																																																																																																		
Oil Cooler	☒ FAIR · Attn																																																																																																																																		
TRANSMISSION & TRAVEL																																																																																																																																			
T/M TYPE	☒ PS · DD																																																																																																																																		
Transmission	☒ FAIR · Attn																																																																																																																																		
Travel	☒ FAIR · Attn																																																																																																																																		
FOOT BRAKE	☒ FAIR · Attn																																																																																																																																		
PARKING BRAKE	FAIR · ☒ Attn	効かない MALFUNCTION																																																																																																																																	
INTERIOR See Photos. 写真参照																																																																																																																																			
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY																																																																																																																																		
Operator's Seat	☒ FAIR · Attn																																																																																																																																		
Glasses	FAIR · ☒ Attn	左ドアガラス欠 LEFT DOOR GLASS: MISSING																																																																																																																																	
AirCon	☒ A/C · H/C · H only · C only · None																																																																																																																																		
FRONT & CYLINDERS																																																																																																																																			
Arm	☒ FAIR · Attn																																																																																																																																		
Bell crank	☒ FAIR · Attn																																																																																																																																		
Bucket	☒ FAIR · Attn																																																																																																																																		
Articulate	☒ FAIR · Attn	ガタあり LOOSE																																																																																																																																	
UNDERCARRIAGE : See Photos. 写真参照																																																																																																																																			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																																																		
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR																																																																																																																																		
COMMENT																																																																																																																																			
オイルパン下周り油漏れ小 BOTTOM OF OIL PAN: OIL LEAKING																																																																																																																																			
ミッション下周り油漏れ小 BOTTOM OF TRANSMISSION: OIL LEAKING																																																																																																																																			
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING																																																																																																																																			
RIDE CONTROL	YES · ☒ NO																																																																																																																																		
ATTACHMENTS																																																																																																																																			
STD BKT	☒ YES · OTHER																																																																																																																																		
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO																																																																																																																																		
COMMENT																																																																																																																																			
左サイドカバーラッチ掛からない、不良																																																																																																																																			
LEFT SIDE COVER LATCH: MALFUNCTION																																																																																																																																			
スピードメーター動作しない SPEED METER: NOT WORKING																																																																																																																																			
HRメーターストップ HR METER: STOPPED																																																																																																																																			
ファンベルト鳴きあり FAN BELT: NOISES																																																																																																																																			
A/C風が出ない A/C: NOT BLOWING AIR																																																																																																																																			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																																																			
3																																																																																																																																			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。