

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/5/30	MAKE	KATO	MODEL	KR-25H-V6
SERIAL No.	PLATE : 5410303		STAMP : KR258-0303		
HR METER	14993	HR	Odometer	66286	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM		
Computer	OK NG	モニター表示不良 MONITOR: NOT DISPLAYING
Swing	FAIR Attn	
Travel	FAIR Attn	*1

TRANSMISSION		
Transmission	FAIR • Attn	
No. OF GEARS	4 GEARS	
4WD	4WD • 6WD	

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only • C only • None

COMMENT
パワーウィンドウ故障あり POWER WINDOW: MALFUNCTION

BOOM		
No. of Section	4	SECTIONS
CRACK/ENFORCEMENT	FAIR	▪ Attn
DERRICKING CYL.	FAIR	▪ Attn
EXTENSION CYL.	FAIR	▪ Attn
JIB	YES	▪ NO
JIB TYPE	STD	▪ PWR
MAIN & SUB WIRE	YES	▪ NO
HOOK	26t, BALL	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1
TIRE WEAR	FAIR • WORN •	UNEVEN WEAR

COMMENT
タイヤ全てサイド亀裂あり ALL TIRE SIDEWALLS: CRACKED

OUTRIGGERS				
OUTRIGGERS	☒	▪	H	
OUTRIGGERS COND.	☐	▪	Attn	
Oil leakage (JACK CYL.)	FRONT		L ▪ R	REAR L ▪ R
Oil leakage (SLIDE CYL.)	FRONT		L ▪ R	REAR L ▪ R

COMMENT	
右Rステアリングシリンダー油漏れあり	
REAR RIGHT STEERING CYLINDER: OIL LEAKING	
*1 公道走行不可 UNABLE TO RUN ON PUBLIC ROADS	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。