

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/6/9	MAKE	KATO	MODEL	KR-25H-ⅢL
SERIAL No.	PLATE : 243485		STAMP : NOT FOUND		
HR METER	30825	HR	Odometer	101069	km
TIRE SIZE	16.00-25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	☐ FAIR · ☐ Attn	
Blow-By	☐ FAIR ☒ A LITTLE ☐ MIDDLE · ☐ SEVERE	
Sound	☐ FAIR · ☐ Attn	
Oil	☐ FAIR · ☐ Attn	
Exhaust Color	☐ FAIR · ☐ Attn	
OPERATION PUMP		
Sound	☐ FAIR · ☐ Attn	
Oil leakage	☐ FAIR · ☐ Attn	
Power	☐ FAIR · ☐ Attn	
COOLING SYSTEM		
Radiator	☐ FAIR · ☐ Attn	
Oil Cooler	☐ FAIR · ☐ Attn	
OPERATING SYSTEM		
Computer	☒ OK · ☐ NG	
Swing	☐ FAIR · ☐ Attn	
Travel	☐ FAIR ☒ *1	
TRANSMISSION		
Transmission	☐ FAIR ☒ *2	
No. OF GEARS	3 GEAR	
4WD	☒ 4WD · ☐ 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	☐ FAIR ☒ 損傷あり DAMAGED	
Glasses	☐ FAIR · ☐ Attn	
AirCon	A/C · H/C · ☒ H only · C only · None	
COMMENT		

BOOM					
No. of Section	4		SECTIONS		
CRACK/ENFORCEMENT	FAIR	▪ Attn			
DERRICKING CYL.	FAIR	▪ Attn			
EXTENSION CYL.	FAIR	▪ Attn			
JIB	YES	▪ NO			
JIB TYPE	STD	▪ PWR			
MAIN & SUB WIRE	YES	▪ NO			
HOO K	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					1
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X	▪ H			
OUTRIGGERS COND.	FAIR	▪ Attn	*3		
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L	R
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT					
*1 公道走行不可 UNABLE TO RUN ON PUBLIC ROADS					
*2 トルコン油漏れあり TORQUE CONVERTER: OIL LEAKING					
*3 右R自然降下あり REAR RIGHT OUTRIGGER: HYDRAULIC DRIFT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。