

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/5/28	MAKE	TADANO	MODEL	TR-200M-4
SERIAL No.	PLATE : 521437		STAMP : TR202-0283		
HR METER	8179	HR	Odometer	72341	km
TIRE SIZE	14.00R24		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · ☒ MIDDLE · ☐ SEVERE	
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · ☒ NG *1	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
TRANSMISSION		
Transmission	☒ FAIR · Attn	
No. OF GEARS	3 GEARS	
4WD	☒ 4WD · ☐ 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	☒ FAIR · Attn	破れあり HUGE CUT
Glasses	☒ FAIR · Attn	
AirCon	A/C · ☒ H/C · H only · C only · None	
COMMENT		
ドアミラー割れあり RIGHT OUTER REAR-VIEW MIRROR: CRACKED		

BOOM				
No. of Section	4	SECTIONS		
CRACK/ENFORCEMENT	☒ FAIR · Attn			
DERRICKING CYL.	☒ FAIR · Attn			
EXTENSION CYL.	☒ FAIR · Attn			
JIB	YES · ☒ NO			
JIB TYPE	STD · PWR			
MAIN & SUB WIRE	☒ YES · NO			
HOOK	20t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				1
TIRE WEAR	FAIR · ☒ WORN · UNEVEN WEAR			
COMMENT				
OUTRIGGERS				
OUTRIGGERS	☒ X · H			
OUTRIGGERS COND.	☒ FAIR · Attn			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R
COMMENT				
*1 PTOセットできない、非常用にて作動				
*1 PTO: NOT WORKING (ABLE TO OPERATE IN THE EMERGENCY MODE)				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。