

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/25	MAKE	CAT	MODEL	320E
SERIAL	NO PLATE		STAMP	CAT0320EKSXE02595	
HR METER	7543 / 7552	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	790G	

ENGINE : MODEL		C6.6	S/N	C8N27466
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	*1	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり CUTS	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG · WRIST
Multi	MULTI · 2 · NO *2
ARM-CRANE	YES · NO プレート、フック欠 NO PLATE, NO HOOK
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
底板欠 SOME UNDER COVER: MISSING	
ブーム下ホースひび割れあり	
SOME HOSES AROUND LOWER PART OF BOOM: CRACKED	
燃料メーター不良、メーター上がらない(燃料レベルが低い表示あり)	
FUEL GAUGE: MALFUNCTION	
(GAUGE NEEDLE: UNABLE TO GO UP,	
"LOW FUEL LEVEL" WARNING DISPLAY)	
バックカメラ不良 BACK MONITOR: MALFUNCTION	
*1 ゴリゴリ感、縦ガタあり、ガタ大 RATTLING, SWING: MUCH LOOSE	
*2 マルチ周り汚れ大 AROUND LEVER: MUCH DIRTY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。