

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2025/6/4	MAKE	KOBELCO	MODEL	SK100W
SERIAL	YE-01?80	SOME LETTER UNREADABLE	STAMP	YE1-1280	
HR METER	5279	HR	Odometer	UNKNOWN	km
CAB/CNP	ROPS CAB / CAB / ROPS	CNP / CNP / NONE	TIRE SIZE	18R19.5	YEAR
					YR

ENGINE : MODEL S/N Oil leakage FAIR · Attn Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound FAIR · Attn Oil FAIR · Attn Exhaust Color FAIR · Attn 白煙あり WHITE FUMES US EPA YES · NO MAIN PUMP Sound FAIR · Attn Oil leakage FAIR · Attn Power FAIR · Attn COOLING SYSTEM Radiator FAIR · Attn Oil Cooler FAIR · Attn OPERATING SYSTEM Swing FAIR · Attn ガタあり SWING: LOOSE Travel FAIR · Attn *1 INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · FAIR · DIRTY Operator's Seat FAIR · Attn Glasses FAIR · Attn 右側割れあり RIGHT SIDE GLASS: CRACKED AirCon A/C · H/C · H only · C only · None BOOM / ARM / BKT Boom FAIR · Attn Boom Cylinder FAIR · Attn *2 Arm FAIR · Attn Arm Cylinder FAIR · Attn BKT FAIR · Attn BKT Cylinder FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2 TIRE WEAR FAIR · WORN · UNEVEN WEAR COMMENT 左右Fダンパーシリンダーにじみあり FRONT DAMPER CYLINDERS: OIL OOZING Rデフ油漏れ小 REAR DIFFERENTIAL: OIL LEAKING BKT STD / SLOPE / NARROW / SKELETON / OTHER () Lever LONG · WRIST Multi MULTI · 2 · NO ARM-CRANE YES · NO BLADE YES · NO OFFSET YES · NO OFFSET Cylinder FAIR · Attn Piping YES · NO Breaker only · Multi OUTRIGGERS COND. FAIR · Attn COMMENT 左サイドカバーラッチ破損あり LEFT SIDE COVER LATCH: BROKEN エアー溜まらない AIR: UNABLE TO STORE A/Cコントロールユニット破損あり、動作しない A/C CONTROL UNIT: BROKEN, A/C: NOT WORKING *1 Pブレーキ、フットブレーキ効かない、パーキング解除してもランプ消えない *1 PARKING BRAKE & FOOT BRAKE: MALFUNCTION, PARKING LAMP: UNABLE TO TURN OFF EVEN RELEASING THE PARKING BRAKE *2 左右サビ、右側油漏れあり *2 CYLINDERS: RUSTY, RIGHT CYLINDER: OIL LEAKING RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。