

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |           |
|-----------------|----------------------------------------|------|---------|-------------------|-----------|
| INSPECTION DATE | 2025/5/30                              | MAKE | KOMATSU | MODEL             | PC650-8E0 |
| SERIAL          | 65442                                  |      | STAMP   | KMTPC233EHC065442 |           |
| HR METER        | 6291                                   | HR   | YEAR    | YR                |           |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 600G              |           |

|                  |                                      |                            |     |        |
|------------------|--------------------------------------|----------------------------|-----|--------|
| ENGINE : MODEL   |                                      | 6D140E-5                   | S/N | 541549 |
| Oil leakage      | (FAIR) · Attn                        |                            |     |        |
| Blow-By          | (FAIR) · Attn                        | A LITTLE · MIDDLE · SEVERE |     |        |
| Sound            | (FAIR) · Attn                        |                            |     |        |
| Oil              | (FAIR) · Attn                        |                            |     |        |
| Exhaust Color    | (FAIR) · Attn                        |                            |     |        |
| US EPA           | YES · (NO)                           |                            |     |        |
| MAIN PUMP        |                                      |                            |     |        |
| Sound            | (FAIR) · Attn                        |                            |     |        |
| Oil leakage      | (FAIR) · Attn                        |                            |     |        |
| Power            | (FAIR) · Attn                        |                            |     |        |
| COOLING SYSTEM   |                                      |                            |     |        |
| Radiator         | (FAIR) · Attn                        |                            |     |        |
| Oil Cooler       | (FAIR) · Attn                        |                            |     |        |
| OPERATING SYSTEM |                                      |                            |     |        |
| Swing            | (FAIR) · Attn                        |                            |     |        |
| Travel           | (FAIR) · Attn                        |                            |     |        |
| INTERIOR         |                                      | See Photos. 写真参照           |     |        |
| INTERIOR COND.   | (CLEAN) · FAIR · DIRTY               |                            |     |        |
| Operator's Seat  | (FAIR) · Attn                        |                            |     |        |
| Glasses          | (FAIR) · Attn                        |                            |     |        |
| AirCon           | (A/C) · H/C · H only · C only · None |                            |     |        |
| BOOM / ARM / BKT |                                      |                            |     |        |
| Boom             | (FAIR) · Attn                        |                            |     |        |
| Boom Cylinder    | (FAIR) · Attn                        |                            |     |        |
| Arm              | (FAIR) · Attn                        |                            |     |        |
| Arm Cylinder     | (FAIR) · Attn                        |                            |     |        |
| BKT              | (FAIR) · Attn                        |                            |     |        |
| BKT Cylinder     | (FAIR) · Attn                        |                            |     |        |

|                                                                      |                                              |                      |  |
|----------------------------------------------------------------------|----------------------------------------------|----------------------|--|
| UNDERCARRIAGE :                                                      |                                              | See Photos. 写真参照     |  |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |                                              | 4                    |  |
| COMMENT                                                              |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
| BKT                                                                  | (STD) / SLOPE / NARROW / SKELETON / OTHER( ) |                      |  |
| Lever                                                                | LONG · (WRIST)                               |                      |  |
| Multi                                                                | MULTI · 2 · (NO)                             |                      |  |
| ARM-CRANE                                                            | YES · (NO)                                   |                      |  |
| BLADE                                                                | YES · (NO)                                   |                      |  |
| OFFSET                                                               | YES · (NO)                                   |                      |  |
| OFFSET Cylinder                                                      | FAIR · Attn                                  |                      |  |
| Piping                                                               | YES · (NO)                                   | Breaker only · Multi |  |
| COMMENT                                                              |                                              |                      |  |
| バックカメラ不良 BACK MONITOR: MALFUNCTION                                   |                                              |                      |  |
| 付属品: ステップ、カバー STEPS & COVERS AS SPARE                                |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
|                                                                      |                                              |                      |  |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |                                              | 4                    |  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。