

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/4	MAKE	KOMATSU	MODEL	PC120-6E
SERIAL	52603		STAMP	PC120-52603	
HR METER	9190	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	ガタ、ヘコミあり LOOSE, DENT
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT 左右トラックローラーガタあり SOME TRACK ROLLERS: LOOSE		
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG ▪ (WRIST)	
Multi	(MULTI) ▪ 2 ▪ NO	
ARM-CRANE	YES ▪ (NO)	
BLADE	YES ▪ (NO)	
OFFSET	YES ▪ (NO)	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	YES ▪ (NO)	Breaker only ▪ Multi
COMMENT A/C冷えない A/C: MALFUNCTION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。