

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/6/2	MAKE	KOBELCO	MODEL	7065
SERIAL No.	PLATE : GG00142	STAMP	00142		
HR METER	3650	HR	SHOE	800FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	ヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	FAIR ☒ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE ☐
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	

OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	

COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	

OPERATING SYSTEM		
Computer	OK ☐ NG ☐	未確認 NOT CHECKED
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	*1

BOOM	
MAIN BOOM	TOP, BOTTOM, 6m × 2, 3m × 2
BOOM TOTAL	30m
TOP SHEAVE	YES ☒ NO ☐
JIB	
TOWER	

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN ☐ FAIR ☐ DIRTY ☒	
Operator's Seat	FAIR ☒ Attn	破れあり CUTS
Glasses	FAIR ☒ Attn	
AirCon	A/C ☐ H/C ☐ H only ☒ C only ☐ None ☐	

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1	

COMMENT	
WEIGHT	2
HOOK	65t, 32t, BALL
LIFTER	YES ☐ NO ☒

COMMENT	
バックストッパー曲がりあり BACK STOPPER: BENT	
*1 アクセル調整できない	
*1 ACCELERATOR: UNABLE TO CONTROL ENGINE SPEED	
@NARITA YARD	
BOOM: TOP, BOTTOM, 6m × 1, 3m × 1	
65t HOOK	
@SAKURA YARD	
BOOM: 6m × 1, 3m × 1	
HOOK: 32t, BALL	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。