## INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DATE		2025	MAKE	IHI			MODE	_	IC100-2		
SERIAL	CB001252					STAMP			CB001252		
HR METER	4451 HR Odometer						m YEA	R		YR	
CAB/CNP	ROPS CA	AB CAB	ROPS	S CNP / CNP /	/ NONE	SHOE		750R	TIRE		
ENGINE :	١	MAIN FRAME									
Oil leakage	FAIR · Attn					MAIN FL	AME	FAIR • A	ttn		
Blow-By	FAIR · Attn	A LITTLE •	MIDDL	E · SEVERE		VESSEL					
Sound	FAIR · Attn					VESSE	L	FAIR • A	ttn		
Oil	FAIR · Attn					REAR GATE	TYPE	NORM	IAL) · L	-GATE (FLAT)	
Exhaust Color	FAIR · Attn					REAR G	ATE	FAIR • A	ttn		
US EPA	YES · NO					UNDERCARRIAGE: See Photos. 写真参照					
OPERATION PUMP						RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					
Sound	FAIR · Attn					TIRE WE	AR	FAIR •	WORN • U	NEVEN WEAR	
Oil leakage	FAIR · Attn					COMMENT	Γ				
Power	FAIR · Attn					ラジエータフ	ノードキ	ーシリンタ	で一固着あり	、回らない、開閉	不可
COOLING SYSTEM						RADIATOR HOOD KEY CYLINDER:					
Radiator	FAIR · Attn					STUCK, U	NABLE	TO ROT	ATE, UNABL	E TO OPEN or	CLOSE
Oil Cooler	FAIR · Attn					*1 少しずつ	右に	曲がる A	LITTLE TO	TTERING TO I	RIGHT
TRANSMISSION & TRAVEL											
T/M TYPE	PS) · DD			No. OF GEARS 2	GEARS						
Transmission	FAIR · Attn										
Travel	FAIR · Attn	*1									
Swing	FAIR · Attn										
Articulate	FAIR · Attn										
FOOT BRAKE	FAIR · Attn										
PARKING BRAKE	FAIR · Attn										
INTERIOR See Photos. 写真参照											
INTERIOR COND.	CLEAN	• FAI	IR •	DIRTY							
Operator's Seat	FAIR) · Attn	破れあり	CUTS								
Glasses	FAIR · Attn										
AirCon	A/C)	H/C ·	H only	• C only •	None	RUST of BODY	(5: NONE	, 4: A LITTLE,	3: MIDDLE, 2: MU	ICH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。