

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/6/9	MAKE	KATO	MODEL	KRM-13H
SERIAL No.	PLATE : 5911020		STAMP : KR130-1020		
HR METER	10619	HR	Odometer	84795	km
TIRE SIZE	11R22.5		YEAR	YR	

[illegible]

BOOM					
No. of Section	6	SECTIONS			
CRACK/ENFORCEMENT	(FAIR)	▪ Attn			
DERRICKING CYL.	(FAIR)	▪ Attn			
EXTENSION CYL.	(FAIR)	▪ Attn			
JIB	(YES)	▪ NO			
JIB TYPE	STD	▪ (PWR)			
MAIN & SUB WIRE	(YES)	▪ NO			
HOOK	13t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR	(FAIR) ▪ WORN ▪ UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X	▪ (H)			
OUTRIGGERS COND.	FAIR	▪ Attn	*1		
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT *1 外の操作ボックスじゃないと動かない *1 ONLY ABLE TO OPERATE FROM OUTSIDE (UNABLE TO OPERATE IN CAB)					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。