

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/5/22	MAKE	KUBOTA	MODEL	RX-505
SERIAL	73001		STAMP	73001	
HR METER	3296	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400R	

ENGINE : MODEL V2203 S/N 7ES8112	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES · ☒ NO
MAIN PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
OPERATING SYSTEM	
Swing	☒ FAIR · Attn ガタあり SWING: LOOSE
Travel	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	☒ FAIR · Attn
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · ☒ None
BOOM / ARM / BKT	
Boom	☒ FAIR · Attn
Boom Cylinder	☒ FAIR · Attn
Arm	☒ FAIR · Attn
Arm Cylinder	☒ FAIR · Attn
BKT	☒ FAIR · Attn
BKT Cylinder	☒ FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	☒ YES · NO
BLADE	☒ YES · NO
OFFSET	☒ YES · NO
OFFSET Cylinder	☒ FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
E/Gフードラッチ不良 ENGINE HOOD LATCH: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。