INSPECTION SHEET 検品書 CRAWLER CRANE クローラクレーン

INSPECTIO	N DATE	2025/5/27	MAKE		MAEDA	MODEL	LC785M-6		
SERIAL No.	AL No. PLATE: 31483		•	STAMP		31483			
HR METER	36	31 HR	SHOE	45	0G PADS	YEAR		YR	
ENGINE :	MODEL	4D95LE-3 S/N	l 128	581	INTERIOR	See Photos.	写真参照		
Oil leakage FAIR · Attn					INTERIOR COND. CLEAN - FAIR - DIRTY				
Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE				Operator's Seat FAIR Attn					
Sound FAIR · Attn				Glasses FAIR Attn					
Oil	FAIR · Attn				AirCon A/	С н/С	· H only · C only ·	None	
Exhaust Color FAIR · Attn *1				UNDERCARRIAGE: See Photos. 写真参照					
OPERATION PUMP					RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4				
Sound FAIR · Attn				COMMENT					
Oil leakage	FAIR · Attn								
Power	FAIR · Attn								
COOLING SYSTEM					WEIGHT				
Radiator	FAIR · Attn				ноок	2.9t			
Oil Cooler	FAIR · Attn				LIFTER	YES · NO			
OPERATING SYSTEM					COMMENT				
Computer	OK)· NG				CAB				
Swing	FAIR · Attn				5段ブーム 5-S	ECTION BO	OM		
Travel FAIR · Attn				*1 入庫時白煙あり(検品中は白煙なし)					
воом				*1 WHITE FUMES WHEN UNLOADING AT THE YARD					
MAIN BOOM				(NO FU	MES AT THE INSPECTION	TIME)			
BOOM TOTAL									
TOP SHEAVE YES . NO									
JIB									
TOW	ER								
					PUST of BODY (5: NO	INE Λ·ΔΙΙΤΤΙΕ 3·	MIDDLE 2: MUCH 1: CORPODED)		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。