

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/4	MAKE	HITACHI	MODEL	ZX30U-5B
SERIAL	HCMADHA0H00051145		STAMP	HCMADHA0H00051145	
HR METER	2346	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	300G PADS	

ENGINE : MODEL 3TNV88 S/N 186717	
Oil leakage	<u>FAIR</u> • Attn
Blow-By	<u>FAIR</u> • Attn A LITTLE • MIDDLE • SEVERE
Sound	<u>FAIR</u> • Attn
Oil	<u>FAIR</u> • Attn
Exhaust Color	<u>FAIR</u> • Attn
US EPA	YES • <u>NO</u>
MAIN PUMP	
Sound	<u>FAIR</u> • Attn
Oil leakage	<u>FAIR</u> • Attn
Power	<u>FAIR</u> • Attn
COOLING SYSTEM	
Radiator	<u>FAIR</u> • Attn
Oil Cooler	<u>FAIR</u> • Attn
OPERATING SYSTEM	
Swing	<u>FAIR</u> • Attn
Travel	<u>FAIR</u> • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY
Operator's Seat	<u>FAIR</u> • Attn
Glasses	FAIR • Attn
AirCon	A/C • H/C • H only • C only • <u>None</u>
BOOM / ARM / BKT	
Boom	<u>FAIR</u> • Attn
Boom Cylinder	<u>FAIR</u> • Attn
Arm	<u>FAIR</u> • Attn
Arm Cylinder	<u>FAIR</u> • Attn
BKT	<u>FAIR</u> • Attn
BKT Cylinder	<u>FAIR</u> • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • <u>WRIST</u>
Multi	<u>MULTI</u> • 2 • NO
ARM-CRANE	YES • <u>NO</u>
BLADE	<u>YES</u> • NO
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	FAIR • Attn
Piping	<u>YES</u> • NO Breaker only • <u>Multi</u>
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。