

INSPECTION SHEET 検品書
ASPHALT FINISHER アスファルトフィニッシャー

INSPECTION DATE	2025/6/4	MAKE	SUMITOMO	MODEL	HA60W-2
SERIAL	A60A2-0218			STAMP	NOT FOUND
HR METER	9947	HR	YEAR	YR	
SHOE		TIRE (REAR)	15.5R25	MAX PAVING WIDTH	6000 mm

ENGINE : MODEL			S/N		
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn	白煙あり WHITE FUMES		
US EPA	YES	NO			
OPERATION PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
TRAVEL	FAIR	Attn			
SCREED(R)	FAIR	Attn	*1		
SCREED(L)	FAIR	Attn	*2		
VIBRATION	FAIR	Attn			
TAMPER	FAIR	Attn			
SPREADER(R)	FAIR	Attn			
SPREADER(L)	FAIR	Attn			
HOPPER(R)	FAIR	Attn	シリンダー油漏れ小 CYLINDER: OIL LEAKING		
HOPPER(L)	FAIR	Attn			
FEEDER	FAIR	Attn			

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	
COMMENT		
SCREED WIDTH		
MAIN SCREED	2.5 m	
WITH AUTO-WIDENER	m	
WITH EXTENSION	6.0 m	
LEVEL SENSOR	YES · NO	
COMMENT		
右スクリード段差調整動作しない		
RIGHT SCREED: UNABLE TO ADJUST SCREED LEVEL DIFFERENCES		
パーキング効かない PARKING BRAKE: MALFUNCTION		
付属品:部材一式 MANY PARTS AS SPARE		
*1 前側リフトシリンダー油漏れ小、伸縮シリンダー傷あり		
*1 FRONT LIFT CYLINDER: OIL LEAKING,		
EXTENSION CYLINDER: SCRATCHED		
*2 伸縮シリンダー傷あり EXTENSION CYLINDER: SCRATCHED		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。