INSPECTION SHEET 検品書 LIFTING PLATFORM 高所作業車

INSPECTIO	N DATE	2025/6/	3 MAKI	MAKE		TADANO		MODEL	AC-125S-1	AC-125S-1	
SERIAL No.	PLATE: HA0058			STAMP: HA0058							
HR METER	989	93 HR	Odometer			_	ļ	km YEAR		YR	
CHASSIS	MODEL –				No.			_			
SHOE	450R				TIRE SIZ	E					
MAX HIGHT	12.5 m			m	MAX WEIG	НТ		750	kg		
ENGINE :	MODEL S/N				INTERIOR See Photos. 写真参照						
Oil leakage	FAIR) · Attn					INTERIOR COND.	CI	LEAN •	FAIR • DIRTY		
Blow-By	FAIR · Attn	A LITTLE • M	IIDDLE · SEV	/ERE		Operator's Seat	FAIR •	Attn			
Sound	FAIR) · Attn					Glasses	FAIR •	Attn			
Oil	FAIR) · Attn					AirCon	A/C	• H/C	· H only · C only ·(None	
Exhaust Color											
US EPA	YES (NO)					RUST (5: NONE	, 4: A L	LITTLE, 3: MID	DDLE, 2: MUCH, 1: CORRODED)	4	
OPERATION PUMP					TIRE WEAR FAIR • WORN • UNEVEN WEAR						
Sound	FAIR · Attn					COMMENT					
Oil leakage	FAIR) · Attn										
Power	FAIR) · Attn										
COOLING SYSTEM					OUTRIGGE	RS	х н				
Radiator	FAIR · Attn					OUTRIGGERS (COND.	FAIR • Attr	1		
Oil Cooler	FAIR • Attn					COMMENT					
TRANSMISSION & TRAVEL					*1 下の操作パネルだと旋回不可、						
T/M TYPE	No. OF GEARS 3 GEARS					デッキ操作パネルだと非常Pを入れないと旋回不可					
Transmission	FAIR · Attn				*1 UNABLE TO OPERATE FROM LOWER PART,						
4WD	4WD • 2WD					ABLE TO C	PERA	TE AT THE	BUCKET IN THE EMERGENC	Y MODE	
Travel	FAIR · Attn										
Swing	FAIR Attn	*1									
FOOT BRAKE	FAIR • Attn										
PARKING BRAKE FAIR • Attn											
воом											
No. of Section 3 SECTIONS											
DERRICKING CYL. FAIR · Attn											
EXTENSION CYL. FAIR) · Attn					RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。