

INSPECTION SHEET 検品書
CRAWLER DRILL クローラドリル

INSPECTION DATE	2025/6/6	MAKE	TOKYO RYUKI	MODEL	CDH-821C
SERIAL	NO PLATE			STAMP	W002161A0
HR METER	8773	HR	YEAR	YR	
CAB/CNP	CAB	/	CNP	/	NONE
SHOE	300G				
DRIFTER MODEL	YH55-9815209				

ENGINE : MODEL	B5.9	S/N	26270455
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM			
Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR	See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR	Attn	損傷あり A LITTLE DAMAGED
Glasses	FAIR	Attn	
AirCon	A/C · H/C · H only · C only · None		

DRIFTER HYDR.			
Lift	FAIR	Attn	*1
Swing	FAIR	Attn	*2
Tilt	FAIR	Attn	
Slide	FAIR	Attn	

UNDERCARRIAGE :	See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

COMMENT			
左走行モーター周りにじみあり			
AROUND LEFT TRAVEL MOTOR: OIL OOZING			
下周り油漏れ小 BOTTOM: OIL LEAKING			

Guide(Slide Length)	1300	mm	
Rod Changer	YES	NO	
Drifter	YES	NO	
Compressor	YES	NO	
Blow	YES	NO	

COMMENT			
作動油タンクにじみあり HYDRAULIC OIL TANK: OIL OOZING			
ドリフターHRメーター欠 HR METER OF DRIFTER: MISSING			
ドリフターホースひび割れあり SOME DRIFTER HOSES: CRACKED			
右サイドカバー欠 RIGHT SIDE COVER: MISSING			

燃料ランプ点灯あり(燃料OK) LOW FUEL WARNING LAMP: ON (FUEL: OK)			
ヒーター&クーラー風が出ない HEATER & COOLER: NOT BLOWING AIR			
*1 ブーム用、ガイド用油漏れあり			
*1 CYLINDERS FOR BOOM & GUIDE: OIL LEAKING			
*2 ブーム用油漏れあり、ガイド用油漏れ小			
*2 CYLINDERS FOR BOOM & GUIDE: OIL LEAKING			

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		
--	---	--	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。