

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/6/4	MAKE	KOBELCO	MODEL	RK160-7
SERIAL No.	PLATE : FW5180		STAMP : T009-5021		
HR METER	21822	HR	Odometer	104601	km
TIRE SIZE	325/95R24		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR (Attn)	オイルパンにじみあり OIL PAN: OIL Oozing	
Blow-By	FAIR (Attn)	A LITTLE ・ MIDDLE (SEVERE)	
Sound	(FAIR) ・ Attn		
Oil	(FAIR) ・ Attn		
Exhaust Color	(FAIR) ・ Attn		
OPERATION PUMP			
Sound	(FAIR) ・ Attn		
Oil leakage	(FAIR) ・ Attn		
Power	(FAIR) ・ Attn		
COOLING SYSTEM			
Radiator	(FAIR) ・ Attn		
Oil Cooler	(FAIR) ・ Attn		
OPERATING SYSTEM			
Computer	(OK) ・ NG		
Swing	(FAIR) ・ Attn		
Travel	(FAIR) ・ Attn		
TRANSMISSION			
Transmission	(FAIR) ・ Attn		
No. OF GEARS	3	GEARS	
4WD	(4WD) ・ 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN ・ (FAIR) ・	DIRTY	
Operator's Seat	(FAIR) ・ Attn		
Glasses	(FAIR) ・ Attn		
AirCon	(A/C) ・ H/C ・ H only ・ C only ・ None		
COMMENT			

BOOM						
No. of Section	6	SECTIONS				
CRACK/ENFORCEMENT	(FAIR)	▪ Attn				
DERRICKING CYL.	(FAIR)	▪ Attn				
EXTENSION CYL.	(FAIR)	▪ Attn				
JIB	(YES)	▪ NO				
JIB TYPE	(STD)	▪ PWR				
MAIN & SUB WIRE	(YES)	▪ NO				
HOOK	16t, BALL					
UNDERCARRIAGE : See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						4
TIRE WEAR	(FAIR) ▪ WORN ▪ UNEVEN WEAR					
COMMENT						
OUTRIGGERS						
OUTRIGGERS	X	▪ (H)				
OUTRIGGERS COND.	(FAIR)	▪ Attn				
Oil leakage (JACK CYL.)	FRONT	(L) ▪ (R)	REAR	(L) ▪ (R)		
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R		
COMMENT						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。