

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/6/6	MAKE	TADANO	MODEL	GR-120N-1
SERIAL No.	PLATE : HD0671			STAMP : TR120-0671	
HR METER	10304	HR	Odometer	105525	km
TIRE SIZE	275/80R22.5	YEAR	2004	YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	

OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	

COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	

OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	

TRANSMISSION		
Transmission	☒ FAIR · Attn	
No. OF GEARS	3 GEARS	
4WD	☒ 4WD · 6WD	

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	FAIR · ☒ Attn	破れあり CUTS
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	

COMMENT

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	☒ FAIR · Attn	
DERRICKING CYL.	☒ FAIR · Attn	
EXTENSION CYL.	☒ FAIR · Attn	
JIB	☒ YES · NO	
JIB TYPE	STD · ☒ PWR	
MAIN & SUB WIRE	☒ YES · NO	
HOOK	4.9t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR

COMMENT
左Fタイヤサイドクラックあり FRONT LEFT TIRE SIDEWALL: CRACKED

OUTRIGGERS				
OUTRIGGERS	X · ☒ H			
OUTRIGGERS COND.	☒ FAIR · Attn			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R

COMMENT	
付属品:タイヤ TIRE AS SPARE	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。