

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/6/5	MAKE	KATO	MODEL	KR-70H-L
SERIAL No.	PLATE : 5210213		STAMP : KRC006-0213		
HR METER	19332	HR	Odometer	44512	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
OPERATION PUMP			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
COOLING SYSTEM			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
OPERATING SYSTEM			
Computer	OK • NG		
Swing	FAIR • Attn		
Travel	FAIR • Attn		
TRANSMISSION			
Transmission	FAIR • Attn		
No. OF GEARS	4	GEARS	
4WD	4WD • 6WD		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR • DIRTY		
Operator's Seat	FAIR • Attn		
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • None		
COMMENT			

BOOM				
No. of Section	6		SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪	Attn	
DERRICKING CYL.	FAIR	▪	Attn	
EXTENSION CYL.	FAIR	▪	Attn	
JIB	YES	▪	NO	
JIB TYPE	STD	▪	PWR	
MAIN & SUB WIRE	YES	▪	NO	
HOOK	48/70t, 34t, BALL, HANGER × 2			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				4
TIRE WEAR	FAIR	▪	WORN ▪ UNEVEN WEAR	
COMMENT				
OUTRIGGERS				
OUTRIGGERS	X	▪	H	
OUTRIGGERS COND.	FAIR	▪	Attn	
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR L ▪ R
COMMENT				
サスペンション警報音あり、サスレベル出ない				
WARNING SOUNDS FOR SUSPENSION: ON,				
MONITOR: UNABLE TO DISPLAY FOR SUSPENSION LEVEL				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。