

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

|                 |                |      |                   |        |           |
|-----------------|----------------|------|-------------------|--------|-----------|
| INSPECTION DATE | 2025/6/13      | MAKE | TADANO            | MODEL  | GR-250N-2 |
| SERIAL No.      | PLATE : FB5695 |      | STAMP : T003-0450 |        |           |
| HR METER        | 28987          | HR   | Odometer          | 118059 | km        |
| TIRE SIZE       | 385/95R25      |      | YEAR              | YR     |           |

|                                       |                                      |                            |
|---------------------------------------|--------------------------------------|----------------------------|
| <b>ENGINE : MODEL</b>                 |                                      | <b>S/N</b>                 |
| Oil leakage                           | (FAIR) · Attn                        |                            |
| Blow-By                               | (FAIR) · Attn                        | A LITTLE · MIDDLE · SEVERE |
| Sound                                 | (FAIR) · Attn                        |                            |
| Oil                                   | (FAIR) · Attn                        |                            |
| Exhaust Color                         | (FAIR) · Attn                        |                            |
| <b>OPERATION PUMP</b>                 |                                      |                            |
| Sound                                 | (FAIR) · Attn                        |                            |
| Oil leakage                           | (FAIR) · Attn                        |                            |
| Power                                 | (FAIR) · Attn                        |                            |
| <b>COOLING SYSTEM</b>                 |                                      |                            |
| Radiator                              | (FAIR) · Attn                        |                            |
| Oil Cooler                            | (FAIR) · Attn                        |                            |
| <b>OPERATING SYSTEM</b>               |                                      |                            |
| Computer                              | (OK) · NG                            |                            |
| Swing                                 | (FAIR) · Attn                        |                            |
| Travel                                | (FAIR) · Attn                        |                            |
| <b>TRANSMISSION</b>                   |                                      |                            |
| Transmission                          | (FAIR) · Attn                        |                            |
| No. OF GEARS                          | 4 GEAR                               |                            |
| 4WD                                   | (4WD) · 6WD                          |                            |
| <b>INTERIOR      See Photos. 写真参照</b> |                                      |                            |
| INTERIOR COND.                        | CLEAN · (FAIR) · DIRTY               |                            |
| Operator's Seat                       | (FAIR) · Attn                        |                            |
| Glasses                               | (FAIR) · Attn                        |                            |
| AirCon                                | (A/C) · H/C · H only · C only · None |                            |
| <b>COMMENT</b>                        |                                      |                            |
|                                       |                                      |                            |
|                                       |                                      |                            |
|                                       |                                      |                            |

|                                                                      |  |                           |  |          |  |      |  |       |  |
|----------------------------------------------------------------------|--|---------------------------|--|----------|--|------|--|-------|--|
| BOOM                                                                 |  |                           |  |          |  |      |  |       |  |
| No. of Section                                                       |  | 4                         |  | SECTIONS |  |      |  |       |  |
| CRACK/ENFORCEMENT                                                    |  | FAIR                      |  | ▪ Attn   |  |      |  |       |  |
| DERRICKING CYL.                                                      |  | FAIR                      |  | ▪ Attn   |  |      |  |       |  |
| EXTENSION CYL.                                                       |  | FAIR                      |  | ▪ Attn   |  |      |  |       |  |
| JIB                                                                  |  | YES                       |  | ▪ NO     |  |      |  |       |  |
| JIB TYPE                                                             |  | STD                       |  | ▪ PWR    |  |      |  |       |  |
| MAIN & SUB WIRE                                                      |  | YES                       |  | ▪ NO     |  |      |  |       |  |
| HOOK                                                                 |  | 25t, BALL                 |  |          |  |      |  |       |  |
| UNDERCARRIAGE : See Photos. 写真参照                                     |  |                           |  |          |  |      |  |       |  |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |  |                           |  |          |  |      |  | 4     |  |
| TIRE WEAR                                                            |  | FAIR • WORN • UNEVEN WEAR |  |          |  |      |  |       |  |
| COMMENT                                                              |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
| OUTRIGGERS                                                           |  |                           |  |          |  |      |  |       |  |
| OUTRIGGERS                                                           |  | X                         |  | ▪ H      |  |      |  |       |  |
| OUTRIGGERS COND.                                                     |  | FAIR                      |  | ▪ Attn   |  |      |  |       |  |
| Oil leakage (JACK CYL.)                                              |  | FRONT                     |  | L ▪ R    |  | REAR |  | L ▪ R |  |
| Oil leakage (SLIDE CYL.)                                             |  | FRONT                     |  | L ▪ R    |  | REAR |  | L ▪ R |  |
| COMMENT                                                              |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
|                                                                      |  |                           |  |          |  |      |  |       |  |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |  |                           |  |          |  |      |  | 4     |  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。