

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/6/9	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB4789		STAMP : TR256-1505		
HR METER	13443	HR	Odometer	95732	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	*1
Blow-By	FAIR ☒ Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Computer	OK ☒ NG	
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	
TRANSMISSION		
Transmission	FAIR ☒ Attn	油漏れあり OIL LEAKING
No. OF GEARS	4 GEARS	
4WD	4WD ☒ 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR ☒ DIRTY	
Operator's Seat	FAIR ☒ Attn	破れあり HUGE CUT
Glasses	FAIR ☒ Attn	
AirCon	A/C ☒ H/C · H only · C only · None	
COMMENT		
A/Cバルブ付近油漏れあり AROUND A/C VALVE: OIL LEAKING		

BOOM				
No. of Section	4	SECTIONS		
CRACK/ENFORCEMENT	FAIR ☒ Attn			
DERRICKING CYL.	FAIR ☒ Attn	ロッド傷あり ROD: SCRATCHED		
EXTENSION CYL.	FAIR ☒ Attn	油漏れあり OIL LEAKING		
JIB	YES ☒ NO			
JIB TYPE	STD ☒ PWR			
MAIN & SUB WIRE	YES ☒ NO			
HOOK	25t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3
TIRE WEAR	FAIR ☒ WORN ☒ UNEVEN WEAR			
COMMENT				
OUTRIGGERS				
OUTRIGGERS	X ☒ H			
OUTRIGGERS COND.	FAIR ☒ Attn			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R
COMMENT				
スイベルにじみあり SWIVEL: OIL Oozing				
*1 E/Gヘッド油漏れあり CYLINDER HEAD: OIL LEAKING				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。