

INSPECTION SHEET 検品書
CRAWLER DRILL クローラドリル

INSPECTION DATE	2025/6/9	MAKE	NIPPON SHARYO	MODEL	DHP-80
SERIAL	C80061			STAMP	NOT FOUND
HR METER	6392	HR	YEAR	YR	
CAB/CNP	CAB	/	CNP	/	NONE
SHOE	750FLAT				
DRIFTER MODEL	-				

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn *1
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C
DRIFTER HYDR.	H only	C only
Lift	FAIR	Attn
Swing	FAIR	Attn
Tilt	FAIR	Attn
Slide	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
動作未確認 OPERATION: NOT CHECKED	
右Rアウトリガーにじみあり REAR RIGHT OUTRIGGER: OIL OOZING	
燃料メーター不良 FUEL GAUGE: MALFUNCTION	
*1 ポンプ下油汚れあり BOTTOM OF PUMP: OIL STAINS	
@YOTSUKAIDO YARD	
LEADER: 5.5m+1.5m, 1.5m+3.7m+1.3m, 3.m+6m+TOP SHEAVE	
BACK STAY: (2m+2.2m+2.6m+3.5m) × 2	
WEIGHT × 2	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。