

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |           |
|-----------------|----------------------------------------|------|---------|-------------------|-----------|
| INSPECTION DATE | 2025/6/2                               | MAKE | KOMATSU | MODEL             | PC200-8N1 |
| SERIAL          | 310422                                 |      | STAMP   | KMTPC197P02310422 |           |
| HR METER        | 9575                                   | HR   | YEAR    | YR                |           |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 800G              |           |

|                                       |       |          |                            |          |
|---------------------------------------|-------|----------|----------------------------|----------|
| <b>ENGINE : MODEL</b>                 |       | 6D107E-1 | <b>S/N</b>                 | 26509465 |
| Oil leakage                           | FAIR  | Attn     | 油汚れあり OIL STAINS           |          |
| Blow-By                               | FAIR  | Attn     | A LITTLE ・ MIDDLE ・ SEVERE |          |
| Sound                                 | FAIR  | Attn     |                            |          |
| Oil                                   | FAIR  | Attn     |                            |          |
| Exhaust Color                         | FAIR  | Attn     |                            |          |
| US EPA                                | YES   | NO       |                            |          |
| <b>MAIN PUMP</b>                      |       |          |                            |          |
| Sound                                 | FAIR  | Attn     |                            |          |
| Oil leakage                           | FAIR  | Attn     |                            |          |
| Power                                 | FAIR  | Attn     |                            |          |
| <b>COOLING SYSTEM</b>                 |       |          |                            |          |
| Radiator                              | FAIR  | Attn     |                            |          |
| Oil Cooler                            | FAIR  | Attn     |                            |          |
| <b>OPERATING SYSTEM</b>               |       |          |                            |          |
| Swing                                 | FAIR  | Attn     | ゴリゴリ感あり RATTLING           |          |
| Travel                                | FAIR  | Attn     |                            |          |
| <b>INTERIOR      See Photos. 写真参照</b> |       |          |                            |          |
| INTERIOR COND.                        | CLEAN | FAIR     | DIRTY                      |          |
| Operator's Seat                       | FAIR  | Attn     | 破れあり CUT                   |          |
| Glasses                               | FAIR  | Attn     |                            |          |
| AirCon                                | A/C   | H/C      | H only                     | C only   |
|                                       |       |          |                            | None     |
| <b>BOOM / ARM / BKT</b>               |       |          |                            |          |
| Boom                                  | FAIR  | Attn     |                            |          |
| Boom Cylinder                         | FAIR  | Attn     |                            |          |
| Arm                                   | FAIR  | Attn     |                            |          |
| Arm Cylinder                          | FAIR  | Attn     | 油漏れあり OIL LEAKING          |          |
| BKT                                   | FAIR  | Attn     | ガタあり LOOSE                 |          |
| BKT Cylinder                          | FAIR  | Attn     |                            |          |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。