

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/6/10	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB4887			STAMP : TR256-1602	
HR METER	15793	HR	Odometer	104687	km
TIRE SIZE	385/95R25			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	FAIR ☒ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE ☐
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Computer	OK ☒ NG ☐	
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	
TRANSMISSION		
Transmission	FAIR ☒ Attn	*1
No. OF GEARS	4 GEARS	
4WD	4WD ☒ 6WD ☐	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☐ FAIR ☒ DIRTY ☐	
Operator's Seat	FAIR ☒ Attn	切れあり CUT
Glasses	FAIR ☒ Attn	
AirCon	A/C ☒ H/C ☐ H only ☐ C only ☐ None ☐	
COMMENT		

BOOM					
No. of Section	4	SECTIONS			
CRACK/ENFORCEMENT	FAIR ☒ Attn				
DERRICKING CYL.	FAIR ☒ Attn				
EXTENSION CYL.	FAIR ☒ Attn				
JIB	YES ☒ NO ☐				
JIB TYPE	STD ☐ PWR ☒				
MAIN & SUB WIRE	YES ☒ NO ☐				
HOOK	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR	FAIR ☒ WORN ☒ UNEVEN WEAR ☐				
COMMENT					
左Fタイヤ亀裂あり FRONT LEFT TIRE: CRACKED					
OUTRIGGERS					
OUTRIGGERS	X ☐ H ☒				
OUTRIGGERS COND.	FAIR ☒ Attn				
Oil leakage (JACK CYL.)	FRONT	L ☐ R ☐	REAR	L ☐ R ☐	
Oil leakage (SLIDE CYL.)	FRONT	L ☐ R ☐	REAR	L ☐ R ☐	
COMMENT					
マフラーエキゾースト付近異音あり					
AROUND EXHAUST PIPE & MUFFLER: NOISES					
*1 ミッション付近にじみあり AROUND TRANSMISSION: OIL OOZING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。