

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/6	MAKE	KOMATSU	MODEL	PC200-7
SERIAL	256462		STAMP	KMTPC049P02256462	
HR METER	16896	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE : MODEL 6D102E-2 S/N					
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	YES	(NO)			
MAIN PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
OPERATING SYSTEM					
Swing	(FAIR)	Attn			
Travel	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	· (FAIR) ·	DIRTY		
Operator's Seat	FAIR	(Attn)	破れ小 CUTS		
Glasses	(FAIR)	Attn			
AirCon	(A/C)	· H/C	· H only	· C only	· None
BOOM / ARM / BKT					
Boom	(FAIR)	Attn			
Boom Cylinder	(FAIR)	Attn			
Arm	(FAIR)	Attn			
Arm Cylinder	(FAIR)	Attn			
BKT	(FAIR)	Attn			
BKT Cylinder	(FAIR)	Attn			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
BKT	STD	(SLOPE)	NARROW / SKELETON / OTHER()		
Lever	LONG	· (WRIST)			
Multi	MULTI	· 2	· (NO)		
ARM-CRANE	YES	· (NO)			
BLADE	YES	· (NO)			
OFFSET	YES	· (NO)			
OFFSET Cylinder	FAIR	▪ Attn			
Piping	YES	· (NO)	Breaker only ▪ Multi		
COMMENT					
底板油漏れあり BOTTOM: OIL LEAKING					
付属品:スタンダードバケット STANDARD BUCKET AS SPARE					
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。