

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/6	MAKE	HITACHI	MODEL	EX60URG
SERIAL	10C-3508			STAMP	10C-3508
HR METER	E4580	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450R

ENGINE : MODEL		S/N		UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	FAIR • Attn			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE		COMMENT	
Sound	FAIR • Attn			両側フレーム補修溶接あり TRACK FRAMES: WELDED	
Oil	FAIR • Attn	多い MUCH OIL		スィベル付近油漏れあり AROUND SWIVEL: OIL LEAKING	
Exhaust Color	FAIR • Attn				
US EPA	YES • NO				
MAIN PUMP				BKT (STD / SLOPE / NARROW / SKELETON / OTHER())	
Sound	FAIR • Attn			Lever	LONG • WRIST
Oil leakage	FAIR • Attn			Multi	MULTI • 2 • NO
Power	FAIR • Attn	やや弱い A LITTLE WEAK POWER		ARM-CRANE	YES • NO
COOLING SYSTEM				BLADE	YES • NO *1
Radiator	FAIR • Attn			OFFSET	YES • NO 動かない NOT WORKING
Oil Cooler	FAIR • Attn			OFFSET Cylinder	FAIR • Attn
OPERATING SYSTEM				Piping	YES • NO Breaker only • Multi
Swing	FAIR • Attn	ガタあり SWING: LOOSE		COMMENT	
Travel	FAIR • Attn			右Fカバー、右カバーヘコミあり RIGHT BODY: DEFORMED	
INTERIOR See Photos. 写真参照				燃料漏れ大 SEVERE FUEL LEAKING	
INTERIOR COND.	CLEAN • FAIR • DIRTY			HRメーターストップ HR METER: STOPPED	
Operator's Seat	FAIR • Attn	破れ大 HUGE CUTS		付属品: フォークグラブ FORK GRAB AS SPARE (55φ × 65mm)	
Glasses	FAIR • Attn	ドア1枚木の板 SOME DOOR GLASS: WOOD BOARD		*1 溶接跡あり、右油漏れ小 WELDED, RIGHT CYLINDER: OIL LEAKING	
AirCon	A/C • H/C • H only • C only • None				
BOOM / ARM / BKT					
Boom	FAIR • Attn				
Boom Cylinder	FAIR • Attn				
Arm	FAIR • Attn				
Arm Cylinder	FAIR • Attn				
BKT	FAIR • Attn	捲れた所に新たに溶接? REPAIRED			
BKT Cylinder	FAIR • Attn	傷あり SCRATCHED			
				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
				3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。