

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/10	MAKE	KOBELCO	MODEL	SK235SRD-2
SERIAL	YF06-02584		STAMP	YF06-02584	
HR METER	11739	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		J05E	S/N
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn	ガタあり SWING: LOOSE	
Travel	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn		
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn		
BKT	FAIR · Attn	穴あり CRACKED	
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()				
Lever	LONG	▪	(WRIST)		
Multi	(MULTI)	▪	2	▪	NO
ARM-CRANE	YES	▪	(NO)		
BLADE	YES	▪	(NO)		
OFFSET	YES	▪	(NO)		
OFFSET Cylinder	FAIR	▪	Attn		
Piping	(YES)	▪	NO	Breaker only	▪ Multi
COMMENT					
ブーム背面ホースひび割れあり SOME HOSE AROUND LOWER PART OF BOOM: CRACKED バックカメラ不良 BACK MONITOR: MALFUNCTION					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。