

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/6/9	MAKE	KAWASAKI	MODEL	KLD65Z II		
SERIAL	65H1-0398			STAMP	65H1-0398		
HR METER	728	HR	Odometer	53375	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5-25		

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn 白煙あり WHITE FUMES
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn
Travel	FAIR	Attn
FOOT BRAKE	FAIR	Attn
PARKING BRAKE	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR · DIRTY
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C · H only · C only · None
FRONT & CYLINDERS		
Arm	FAIR	Attn
Bell crank	FAIR	Attn
Bucket	FAIR	Attn
Articulate	FAIR	Attn *1

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER スノーブレード SNOW BLADE
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
ヒーター風出ない HEATER: NOT BLOWING AIR	
*1 中折れ周り油漏れあり AROUND ARTICULATE PART: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。