INSPECTION SHEET 検品書 CRAWLER CRANE クローラクレーン

INSPECTION	I DATE	2025/6/10	MAKE		IHI	MODEL	CCH900-6C	
SERIAL No. PLATE: HJ30					STAMP		HJ30	
HR METER	64	02 HR	SHOE	8	300FLAT	YEAR		YR
ENGINE: MODEL S/N					INTERIOR See Photos. 写真参照			
Oil leakage FAIR · Attn					INTERIOR COND. CLEAN - FAIR - DIRTY			
Blow-By FAIR ALITTLE MIDDLE SEVERE				Operator's Seat FAIR Attn				
Sound FAIR · Attn					Glasses FAIR Attn			
Oil F	AIR) · Attn				AirCon A/	C H/C	· H only · C only ·	None
Exhaust Color	AIR) · Attn				UNDERCARRIA	∖GE : See	Photos. 写真参照	
OPERATION PUMP				RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				
Sound FAIR · Attn				COMMENT				
Oil leakage	AIR) · Attn							
Power F	AIR) · Attn							
COOLING SYSTEM				WEIGHT	5	5		
Radiator [F/	AIR) · Attn				ноок	90t, 50t, 30	Ot, BALL	
Oil Cooler FAIR · Attn				LIFTER	YES · NO			
OPERATING SYSTEM					COMMENT			
Computer	ok)∙ ng				タワー部材すべ	て欠品 ALL	. TOWER PARTS: MISSIN	1G
Swing F	AIR) · Attn							
Travel FAIR · Attn				@NARITA YARD				
воом				BOOM: TOP, BOTTOM, 9m×1				
MAIN BOOM TOP, BOTTOM, 9m×4, 6m×2, 3m×2		3m × 2	HOOK: 50t, BALL					
воом то	TAL	61m						
					@SHIROI YARD			
TOP SHEAVE YES · NO				BOOM: 9m×3, 6m×2, 3m×2				
JIB					HOOK: 90t, 30t			
TOWER	R							
					RUST of BODY (5: NO	NE. 4: A LITTLE. 3:	MIDDLE. 2: MUCH. 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。