

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/9	MAKE	CAT	MODEL	311DRR
SERIAL	CAT0311DTAKW01295			STAMP	CAT0311DTAKW01295
HR METER	3859/3859	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL S/N <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Oil leakage</td> <td style="width: 10%;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Blow-By</td> <td>FAIR</td> <td>Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES</td> <td>NO</td> <td></td> </tr> </table> MAIN PUMP <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Sound</td> <td style="width: 10%;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil leakage</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Power</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> </table> COOLING SYSTEM <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Radiator</td> <td style="width: 10%;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil Cooler</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> </table> OPERATING SYSTEM <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Swing</td> <td style="width: 10%;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Travel</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> </table> INTERIOR See Photos. 写真参照 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">INTERIOR COND.</td> <td style="width: 10%;">CLEAN</td> <td style="width: 10%;">FAIR</td> <td style="width: 65%;">DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td>FAIR</td> <td>Attn</td> <td>破れあり CUTS</td> </tr> <tr> <td>Glasses</td> <td>FAIR</td> <td>Attn</td> <td>ヒビ割れあり WINDSHIELDS: CRACKED</td> </tr> <tr> <td>AirCon</td> <td>A/C</td> <td>H/C</td> <td>H only · C only · None</td> </tr> </table> BOOM / ARM / BKT <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">Boom</td> <td style="width: 10%;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;">腐食あり CORRODED</td> </tr> <tr> <td>Boom Cylinder</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Arm</td> <td>FAIR</td> <td>Attn</td> <td>腐食あり CORRODED</td> </tr> <tr> <td>Arm Cylinder</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>BKT</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>BKT Cylinder</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> </table>	Oil leakage	FAIR	Attn		Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	Sound	FAIR	Attn		Oil	FAIR	Attn		Exhaust Color	FAIR	Attn		US EPA	YES	NO		Sound	FAIR	Attn		Oil leakage	FAIR	Attn		Power	FAIR	Attn		Radiator	FAIR	Attn		Oil Cooler	FAIR	Attn		Swing	FAIR	Attn		Travel	FAIR	Attn		INTERIOR COND.	CLEAN	FAIR	DIRTY	Operator's Seat	FAIR	Attn	破れあり CUTS	Glasses	FAIR	Attn	ヒビ割れあり WINDSHIELDS: CRACKED	AirCon	A/C	H/C	H only · C only · None	Boom	FAIR	Attn	腐食あり CORRODED	Boom Cylinder	FAIR	Attn		Arm	FAIR	Attn	腐食あり CORRODED	Arm Cylinder	FAIR	Attn		BKT	FAIR	Attn		BKT Cylinder	FAIR	Attn		UNDERCARRIAGE : See Photos. 写真参照 <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 85%;">RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="width: 15%;">3</td> </tr> </table> COMMENT トラックフレーム加修あり TRACK FRAMES: REPAIRED <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 15%;">BKT</td> <td style="width: 10%;">STD</td> <td style="width: 10%;">SLOPE</td> <td style="width: 10%;">NARROW</td> <td style="width: 10%;">SKELETON</td> <td style="width: 10%;">OTHER</td> <td style="width: 45%;"></td> </tr> <tr> <td>Lever</td> <td>LONG</td> <td>WRIST</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Multi</td> <td>MULTI</td> <td>2</td> <td>NO</td> <td></td> <td></td> <td></td> </tr> <tr> <td>ARM-CRANE</td> <td>YES</td> <td>NO</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>BLADE</td> <td>YES</td> <td>NO</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>OFFSET</td> <td>YES</td> <td>NO</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>OFFSET Cylinder</td> <td>FAIR</td> <td>Attn</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>Piping</td> <td>YES</td> <td>NO</td> <td>Breaker only</td> <td>Multi</td> <td></td> <td></td> </tr> </table> COMMENT リペイントあり REPAINTED モニター劣化あり MONITOR: DETERIORATED バックカメラ不良 BACK CAMERA: MALFUNCTION バッテリー充電異常点灯あり BATTERY WARNING LAMP: ON A/Cベルト欠品 A/C BELT: MISSING A/Cコンプレッサー固着あり A/C COMPRESSOR: STUCK <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 85%;">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="width: 15%;">1</td> </tr> </table>	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	BKT	STD	SLOPE	NARROW	SKELETON	OTHER		Lever	LONG	WRIST					Multi	MULTI	2	NO				ARM-CRANE	YES	NO					BLADE	YES	NO					OFFSET	YES	NO					OFFSET Cylinder	FAIR	Attn					Piping	YES	NO	Breaker only	Multi			RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
Oil leakage	FAIR	Attn																																																																																																																																																							
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE																																																																																																																																																						
Sound	FAIR	Attn																																																																																																																																																							
Oil	FAIR	Attn																																																																																																																																																							
Exhaust Color	FAIR	Attn																																																																																																																																																							
US EPA	YES	NO																																																																																																																																																							
Sound	FAIR	Attn																																																																																																																																																							
Oil leakage	FAIR	Attn																																																																																																																																																							
Power	FAIR	Attn																																																																																																																																																							
Radiator	FAIR	Attn																																																																																																																																																							
Oil Cooler	FAIR	Attn																																																																																																																																																							
Swing	FAIR	Attn																																																																																																																																																							
Travel	FAIR	Attn																																																																																																																																																							
INTERIOR COND.	CLEAN	FAIR	DIRTY																																																																																																																																																						
Operator's Seat	FAIR	Attn	破れあり CUTS																																																																																																																																																						
Glasses	FAIR	Attn	ヒビ割れあり WINDSHIELDS: CRACKED																																																																																																																																																						
AirCon	A/C	H/C	H only · C only · None																																																																																																																																																						
Boom	FAIR	Attn	腐食あり CORRODED																																																																																																																																																						
Boom Cylinder	FAIR	Attn																																																																																																																																																							
Arm	FAIR	Attn	腐食あり CORRODED																																																																																																																																																						
Arm Cylinder	FAIR	Attn																																																																																																																																																							
BKT	FAIR	Attn																																																																																																																																																							
BKT Cylinder	FAIR	Attn																																																																																																																																																							
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																																																																								
BKT	STD	SLOPE	NARROW	SKELETON	OTHER																																																																																																																																																				
Lever	LONG	WRIST																																																																																																																																																							
Multi	MULTI	2	NO																																																																																																																																																						
ARM-CRANE	YES	NO																																																																																																																																																							
BLADE	YES	NO																																																																																																																																																							
OFFSET	YES	NO																																																																																																																																																							
OFFSET Cylinder	FAIR	Attn																																																																																																																																																							
Piping	YES	NO	Breaker only	Multi																																																																																																																																																					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1																																																																																																																																																								

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。