

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |       |        |
|-----------------|----------------------------------------|------|---------|-------|--------|
| INSPECTION DATE | 2025/8/20                              | MAKE | KOMATSU | MODEL | PC40-6 |
| SERIAL          | 13182                                  |      | STAMP   | 13182 |        |
| HR METER        | 9966 HR                                |      | YEAR    | YR    |        |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 400R  |        |

|                           |       |       |                                 |        |       |
|---------------------------|-------|-------|---------------------------------|--------|-------|
| ENGINE :                  |       | MODEL | 3D95S                           | S/N    | 20005 |
| Oil leakage               | FAIR  | Attn  |                                 |        |       |
| Blow-By                   | FAIR  | Attn  | A LITTLE · MIDDLE · SEVERE      |        |       |
| Sound                     | FAIR  | Attn  |                                 |        |       |
| Oil                       | FAIR  | Attn  |                                 |        |       |
| Exhaust Color             | FAIR  | Attn  | 白煙あり WHITE FUMES                |        |       |
| US EPA                    | YES   | NO    |                                 |        |       |
| MAIN PUMP                 |       |       |                                 |        |       |
| Sound                     | FAIR  | Attn  |                                 |        |       |
| Oil leakage               | FAIR  | Attn  | ホースにじみあり SOME HOSES: OIL OOZING |        |       |
| Power                     | FAIR  | Attn  |                                 |        |       |
| COOLING SYSTEM            |       |       |                                 |        |       |
| Radiator                  | FAIR  | Attn  |                                 |        |       |
| Oil Cooler                | FAIR  | Attn  |                                 |        |       |
| OPERATING SYSTEM          |       |       |                                 |        |       |
| Swing                     | FAIR  | Attn  | ガタあり SWING: LOOSE               |        |       |
| Travel                    | FAIR  | Attn  |                                 |        |       |
| INTERIOR See Photos. 写真参照 |       |       |                                 |        |       |
| INTERIOR COND.            | CLEAN | FAIR  | DIRTY                           |        |       |
| Operator's Seat           | FAIR  | Attn  | 破れあり TORN                       |        |       |
| Glasses                   | FAIR  | Attn  | *1                              |        |       |
| AirCon                    | A/C   | H/C   | H only                          | C only | None  |
| BOOM / ARM / BKT          |       |       |                                 |        |       |
| Boom                      | FAIR  | Attn  |                                 |        |       |
| Boom Cylinder             | FAIR  | Attn  |                                 |        |       |
| Arm                       | FAIR  | Attn  |                                 |        |       |
| Arm Cylinder              | FAIR  | Attn  |                                 |        |       |
| ATTACHMENT                | FAIR  | Attn  | ガタあり LOOSE                      |        |       |
| BKT Cylinder              | FAIR  | Attn  |                                 |        |       |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。