

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |        |       |         |
|-----------------|----------------------------------------|------|--------|-------|---------|
| INSPECTION DATE | 2025/7/16                              | MAKE | YANMAR | MODEL | VIO20-3 |
| SERIAL          | 39935                                  |      |        | STAMP | 39935   |
| HR METER        | 7307                                   | HR   | YEAR   | YR    |         |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |        | SHOE  | 250R    |

|                           |       |      |                                |
|---------------------------|-------|------|--------------------------------|
| ENGINE : MODEL            |       | S/N  | D5257                          |
| Oil leakage               | FAIR  | Attn |                                |
| Blow-By                   | FAIR  | Attn | A LITTLE · MIDDLE · SEVERE     |
| Sound                     | FAIR  | Attn |                                |
| Oil                       | FAIR  | Attn |                                |
| Exhaust Color             | FAIR  | Attn |                                |
| US EPA                    | YES   | NO   |                                |
| MAIN PUMP                 |       |      |                                |
| Sound                     | FAIR  | Attn |                                |
| Oil leakage               | FAIR  | Attn |                                |
| Power                     | FAIR  | Attn |                                |
| COOLING SYSTEM            |       |      |                                |
| Radiator                  | FAIR  | Attn |                                |
| Oil Cooler                | FAIR  | Attn |                                |
| OPERATING SYSTEM          |       |      |                                |
| Swing                     | FAIR  | Attn |                                |
| Travel                    | FAIR  | Attn | 2速不良 2nd GEAR: MALFUNCTION     |
| INTERIOR See Photos. 写真参照 |       |      |                                |
| INTERIOR COND.            | CLEAN | FAIR | DIRTY                          |
| Operator's Seat           | FAIR  | Attn | 破れあり CUTS                      |
| Glasses                   | FAIR  | Attn |                                |
| AirCon                    | A/C   | H/C  | H only · C only · None         |
| BOOM / ARM / BKT          |       |      |                                |
| Boom                      | FAIR  | Attn | ガタ大 MUCH LOOSE                 |
| Boom Cylinder             | FAIR  | Attn |                                |
| Arm                       | FAIR  | Attn |                                |
| Arm Cylinder              | FAIR  | Attn |                                |
| BKT                       | FAIR  | Attn | コンクリート付着大 MUCH CONCRETE STAINS |
| BKT Cylinder              | FAIR  | Attn |                                |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。