

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/6/12	MAKE	KOBELCO	MODEL	RK250-7
SERIAL No.	PLATE : EE02-10035		STAMP : EE02-10035		
HR METER	22066	HR	Odometer	137765	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	
TRANSMISSION			
Transmission	FAIR	Attn	
No. OF GEARS	2	GEARS	
4WD	4WD	6WD	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR ·	DIRTY	
Operator's Seat	FAIR	Attn	破れあり HUGE CUTS
Glasses	FAIR	Attn	
AirCon	A/C ·	H/C · H only · C only · None	
COMMENT			

BOOM					
No. of Section	6		SECTIONS		
CRACK/ENFORCEMENT	FAIR	▪ Attn			
DERRICKING CYL.	FAIR	▪ Attn			
EXTENSION CYL.	FAIR	▪ Attn			
JIB	YES	▪ NO			
JIB TYPE	STD	▪ PWR			
MAIN & SUB WIRE	YES	▪ NO			
HOOK	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4				
TIRE WEAR	FAIR • WORN • UNEVEN WEAR				
COMMENT					
左右Fサスシリンダーにじみあり					
FRONT SUSPENSION CYLINDERS: OIL OOZING					
OUTRIGGERS					
OUTRIGGERS	X	▪ H			
OUTRIGGERS COND.	FAIR	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT					
*1 E/Gヘッド油漏れあり CYLINDER HEAD: OIL LEAKING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。