

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/8	MAKE	KOMATSU	MODEL	PC120-11
SERIAL	91248		STAMP	KMTPC265ELA091248	
HR METER	6536	HR	YEAR	2020	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL 4D95LE-7 S/N 816280					
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	YES · (NO)				
MAIN PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
OPERATING SYSTEM					
Swing	(FAIR)	Attn			
Travel	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	(CLEAN)	FAIR · DIRTY			
Operator's Seat	(FAIR)	Attn			
Glasses	(FAIR)	Attn			
AirCon	(A/C) · H/C · H only · C only · None				
BOOM / ARM / BKT					
Boom	(FAIR)	Attn			
Boom Cylinder	(FAIR)	Attn			
Arm	(FAIR)	Attn			
Arm Cylinder	(FAIR)	Attn			
ATTACHMENT	(FAIR)	Attn			
BKT Cylinder	(FAIR)	Attn			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4
COMMENT 					
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()			
Lever	LONG · (WRIST)				
Multi	MULTI · 2 · (NO)				
ARM-CRANE	(YES) · NO				
BLADE	YES · (NO)				
OFFSET	YES · (NO)				
OFFSET Cylinder	FAIR · Attn				
Piping	YES · (NO)	Breaker only · Multi			
COMMENT L01油圧系統異常警告あり “L01” ERROR DISPLAY FOR HYDRAULIC SYSTEM 					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。