

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |                                        |      |      |       |           |
|-----------------|----------------------------------------|------|------|-------|-----------|
| INSPECTION DATE | 2025/7/16                              | MAKE | KATO | MODEL | HD820E-LC |
| SERIAL          | 7076693                                |      |      | STAMP | 6693      |
| HR METER        | 9081                                   | HR   | YEAR | YR    |           |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |      | SHOE  | 600G      |

**ENGINE : MODEL** 6D34 **S/N** 070815

|               |      |      |                        |
|---------------|------|------|------------------------|
| Oil leakage   | FAIR | Attn | 油汚れあり OIL STAINS       |
| Blow-By       | FAIR | Attn | A LITTLE MIDDLE SEVERE |
| Sound         | FAIR | Attn |                        |
| Oil           | FAIR | Attn |                        |
| Exhaust Color | FAIR | Attn |                        |
| US EPA        | YES  | NO   |                        |

**MAIN PUMP**

|             |      |      |  |
|-------------|------|------|--|
| Sound       | FAIR | Attn |  |
| Oil leakage | FAIR | Attn |  |
| Power       | FAIR | Attn |  |

**COOLING SYSTEM**

|            |      |      |  |
|------------|------|------|--|
| Radiator   | FAIR | Attn |  |
| Oil Cooler | FAIR | Attn |  |

**OPERATING SYSTEM**

|        |      |      |  |
|--------|------|------|--|
| Swing  | FAIR | Attn |  |
| Travel | FAIR | Attn |  |

**INTERIOR See Photos. 写真参照**

|                 |       |      |                    |
|-----------------|-------|------|--------------------|
| INTERIOR COND.  | CLEAN | FAIR | DIRTY              |
| Operator's Seat | FAIR  | Attn | 穴あり HOLES          |
| Glasses         | FAIR  | Attn |                    |
| AirCon          | A/C   | H/C  | H only C only None |

**BOOM / ARM / BKT**

|               |      |      |            |
|---------------|------|------|------------|
| Boom          | FAIR | Attn |            |
| Boom Cylinder | FAIR | Attn |            |
| Arm           | FAIR | Attn |            |
| Arm Cylinder  | FAIR | Attn |            |
| BKT           | FAIR | Attn | ガタあり LOOSE |
| BKT Cylinder  | FAIR | Attn |            |

**UNDERCARRIAGE : See Photos. 写真参照**

|                                                              |   |
|--------------------------------------------------------------|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4 |
|--------------------------------------------------------------|---|

**COMMENT**

.....

.....

.....

.....

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ( )

Lever LONG WRIST

Multi MULTI 2 NO

ARM-CRANE YES NO

BLADE YES NO

OFFSET YES NO

OFFSET Cylinder FAIR Attn

Piping YES NO Breaker only Multi

**COMMENT**

A/C操作パネル操作不可(OFFのまま動かない)  
A/C OPERATION PANEL: UNABLE TO OPERATE (UNABLE TO TURN ON)

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。