

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/7/3	MAKE	CAT	MODEL	902C2
SERIAL	CAT0902CPYKT01119			STAMP	CAT0902CPYKT01119
HR METER	27360	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	15.5/60-18 8PR

<table style="width: 100%;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> </tr> <tr> <td>Blow-By</td> <td>FAIR · Attn A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil</td> <td>FAIR · Attn</td> </tr> <tr> <td>Exhaust Color</td> <td>FAIR · Attn</td> </tr> <tr> <td>US EPA</td> <td>YES · NO</td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR · Attn</td> </tr> <tr> <td>Power</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>FAIR · Attn</td> </tr> <tr> <td>Oil Cooler</td> <td>FAIR · Attn</td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>PS · DD</td> </tr> <tr> <td>Transmission</td> <td>FAIR · Attn</td> </tr> <tr> <td>Travel</td> <td>FAIR · Attn</td> </tr> <tr> <td>FOOT BRAKE</td> <td>FAIR · Attn</td> </tr> <tr> <td>PARKING BRAKE</td> <td>FAIR · Attn *1</td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · FAIR · DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td>FAIR · Attn 破れあり CUTS</td> </tr> <tr> <td>Glasses</td> <td>FAIR · Attn</td> </tr> <tr> <td>AirCon</td> <td>A/C · H/C · H only · C only · None</td> </tr> <tr> <td colspan="2">FRONT & CYLINDERS</td> </tr> <tr> <td>Arm</td> <td>FAIR · Attn *2</td> </tr> <tr> <td>Bell crank</td> <td>FAIR · Attn</td> </tr> <tr> <td>Bucket</td> <td>FAIR · Attn</td> </tr> <tr> <td>Articulate</td> <td>FAIR · Attn ガタあり LOOSE</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage	FAIR · Attn	Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE	Sound	FAIR · Attn	Oil	FAIR · Attn	Exhaust Color	FAIR · Attn	US EPA	YES · NO	OPERATION PUMP		Sound	FAIR · Attn	Oil leakage	FAIR · Attn	Power	FAIR · Attn	COOLING SYSTEM		Radiator	FAIR · Attn	Oil Cooler	FAIR · Attn	TRANSMISSION & TRAVEL		T/M TYPE	PS · DD	Transmission	FAIR · Attn	Travel	FAIR · Attn	FOOT BRAKE	FAIR · Attn	PARKING BRAKE	FAIR · Attn *1	INTERIOR See Photos. 写真参照		INTERIOR COND.	CLEAN · FAIR · DIRTY	Operator's Seat	FAIR · Attn 破れあり CUTS	Glasses	FAIR · Attn	AirCon	A/C · H/C · H only · C only · None	FRONT & CYLINDERS		Arm	FAIR · Attn *2	Bell crank	FAIR · Attn	Bucket	FAIR · Attn	Articulate	FAIR · Attn ガタあり LOOSE	<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE : See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>2</td> </tr> <tr> <td colspan="2">TIRE WEAR FAIR · WORN · UNEVEN WEAR</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING</td> </tr> <tr> <td>RIDE CONTROL</td> <td>YES · NO</td> </tr> <tr> <td colspan="2">ATTACHMENTS</td> </tr> <tr> <td>STD BKT</td> <td>YES · OTHER</td> </tr> <tr> <td>BLADE</td> <td>YES · NO Piping for Tilt YES · NO</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">*1 効かない(ワイヤー断線あり) MALFUNCTION (WIRE: DISCONNECTING)</td> </tr> <tr> <td colspan="2">*2 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING</td> </tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">2</td> </tr> </table>	UNDERCARRIAGE : See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR FAIR · WORN · UNEVEN WEAR		COMMENT		STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING		RIDE CONTROL	YES · NO	ATTACHMENTS		STD BKT	YES · OTHER	BLADE	YES · NO Piping for Tilt YES · NO	COMMENT		*1 効かない(ワイヤー断線あり) MALFUNCTION (WIRE: DISCONNECTING)		*2 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2	
ENGINE : MODEL	S/N																																																																																								
Oil leakage	FAIR · Attn																																																																																								
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE																																																																																								
Sound	FAIR · Attn																																																																																								
Oil	FAIR · Attn																																																																																								
Exhaust Color	FAIR · Attn																																																																																								
US EPA	YES · NO																																																																																								
OPERATION PUMP																																																																																									
Sound	FAIR · Attn																																																																																								
Oil leakage	FAIR · Attn																																																																																								
Power	FAIR · Attn																																																																																								
COOLING SYSTEM																																																																																									
Radiator	FAIR · Attn																																																																																								
Oil Cooler	FAIR · Attn																																																																																								
TRANSMISSION & TRAVEL																																																																																									
T/M TYPE	PS · DD																																																																																								
Transmission	FAIR · Attn																																																																																								
Travel	FAIR · Attn																																																																																								
FOOT BRAKE	FAIR · Attn																																																																																								
PARKING BRAKE	FAIR · Attn *1																																																																																								
INTERIOR See Photos. 写真参照																																																																																									
INTERIOR COND.	CLEAN · FAIR · DIRTY																																																																																								
Operator's Seat	FAIR · Attn 破れあり CUTS																																																																																								
Glasses	FAIR · Attn																																																																																								
AirCon	A/C · H/C · H only · C only · None																																																																																								
FRONT & CYLINDERS																																																																																									
Arm	FAIR · Attn *2																																																																																								
Bell crank	FAIR · Attn																																																																																								
Bucket	FAIR · Attn																																																																																								
Articulate	FAIR · Attn ガタあり LOOSE																																																																																								
UNDERCARRIAGE : See Photos. 写真参照																																																																																									
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2																																																																																								
TIRE WEAR FAIR · WORN · UNEVEN WEAR																																																																																									
COMMENT																																																																																									
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING																																																																																									
RIDE CONTROL	YES · NO																																																																																								
ATTACHMENTS																																																																																									
STD BKT	YES · OTHER																																																																																								
BLADE	YES · NO Piping for Tilt YES · NO																																																																																								
COMMENT																																																																																									
*1 効かない(ワイヤー断線あり) MALFUNCTION (WIRE: DISCONNECTING)																																																																																									
*2 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING																																																																																									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																									
2																																																																																									

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。