

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/19	MAKE	HITACHI	MODEL	ZX135USK-5B
SERIAL	HCMDAEA1C00101302		STAMP	HCMDAEA1C00101302	
HR METER	4833	HR	YEAR	2017	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		4JJ1	S/N	222675
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn	*1	
AirCon	A/C	H/C · H only · C only · None		
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT 	
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG ▪ (WRIST)
Multi	(MULTI) ▪ 2 ▪ NO
ARM-CRANE	YES ▪ (NO)
BLADE	YES ▪ (NO)
OFFSET	YES ▪ (NO)
OFFSET Cylinder	FAIR ▪ Attn
Piping	(YES) ▪ NO Breaker only ▪ (Multi)
COMMENT 右Fサイドカバー：手すりとぶつかって開閉不可 FRONT RIGHT SIDE COVER: UNABLE TO OPEN DUE TO HIT A HANDRAIL CABフレーム曲がりあり CAB FRAME: A LITTLE DEFORMED *1 左R、右側ガラスコーキング跡あり *1 REAR LEFT SIDE GLASS & RIGHT SIDE GLASS: TRACE OF CAULKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。