

INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2025/7/11	MAKE	KOMATSU	MODEL	GD705A-4A				
SERIAL	11092			STAMP	G70A4A-11092				
HR METER	5149	HR	Odometer	54649	km	YEAR	1986	YR	
SCARIFIER	YES	NO	0		BLADE	4010			mm
CAB/CNP	CAB	CNP	NONE		TIRE SIZE	14.00-24 20PR (SNOW, SPIKE)			

ENGINE :	MODEL	6D125-1	S/N	20998
Oil leakage	FAIR · Attn	にじみあり OIL OOZING		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
OPERATION PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	PS · DD			
Transmission	FAIR · Attn	バルブ油漏れあり VALVE: OIL LEAKING		
Travel	FAIR · Attn	7、8走行未確認 7th & 8th GEARS: NOT CHECKED		
FOOT BRAKE	FAIR · Attn			
PARKING BRAKE	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn	破れあり、2シート HUGE CUTS, 2 SEATS		
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
HYD. CYLINDER				
For Blade	FAIR · Attn	*1		
For Scarifier	FAIR · Attn	ツメ欠、溶接あり NO RIPPERS, WELDED		
Articulate	FAIR · Attn	*2		
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3
TIRE WEAR		FAIR · WRN · UNEVEN WEAR		
COMMENT				
タコメーター TACHOMETER: 17682km				
燃料メーター不良 FUEL GAUGE: MALFUNCTION				
左フステアリングシリンダー油漏れあり(吸着マットあり)				
FRONT LEFT STEERING CYLINDER: OIL LEAKING (W/ABSORPTION MAT)				
右フステアリングシリンダーにじみあり(吸着マットあり)				
FRONT RIGHT STEERING CYLINDER: OIL OOZING (W/ABSORPTION MAT)				
フリーニングシリンダーにじみあり(吸着マットあり)				
FRONT LEANING CYLINDER: OIL OOZING (W/ABSORPTION MAT)				
コントロールバルブ付近にじみあり				
AROUND CONTROL VALVE: OIL OOZING				
*1 サイドシフトシリンダー油漏れあり(吸着マットあり)				
*1 SIDE SHIFT CYLINDER: OIL LEAKING (W/ABSORPTION MAT)				
*2 左右シリンダーにじみあり CYLINDERS: OIL OOZING				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。